

bpc ORR

SNDR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: GBC2227K

Make & Model: Nissan Urvan

Chassis number: JN1MGSe25Z0796319

Date of survey: _____

Name of surveyor: _____

Contacts: _____

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ 2,101.40
2	Tailgate inner trim board	1	\$ 189.00
3	Tailgate inner trim board clips	1set	\$ -50.00
4	Tailgate lock	1	\$ 261.60
5	Tailgate lock catch	1	\$ 35.10
6	Tailgate weatherstrip	1	\$ 156.70
7	Tailgate outer moulding	1	\$ 287.30
8	Rear bumper	1	\$ 807.60
9	Rear bumper clips	1set	\$ 30.00 60.00
10	Rear bumper RH side retainer	1	\$ 53.00
11	Rear bumper LH side retainer	1	\$ 53.00
12	End panel (outer)	1	\$ 487.30
13	End panel (inner)	1	\$ 555.60
14	End panel top aluminium strip	1	\$ 220.80
15	RH taillamp assy	1	\$ 303.40
16	RH taillamp panel	1	\$ 543.40
17	RH taillamp lock clips	1set	\$ 28.00
18	Exhaust silencer	1	\$ 771.90
19	Exhaust silencer gasket	1	\$ 45.00
20	RH side panel	1	\$ 2,438.04
21	RH side panel air vent	1	\$ 58.80
22	RH side panel petrol cover	1	\$ 124.60
23	RH side panel petrol inner garnish	1	\$ 101.20
24	RH side panel inner trim board	1	\$ 442.10
25	RH side panel inner trim board clips	1set	\$ 40.00
26	RH sliding door railing	1	\$ 372.10
27	RH sliding door railing side cover	1	\$ 43.70

\$ 10,630.64
 Parts less 10% \$ 1,063.06
 Total \$ 9,567.58

No.	Special Nett Items	Amount S\$
1	Tailgate windscreen glass sealant	\$ 40.00 70.00

DD ✓ 1816.00
 BR ✓ HW
 NN ✓
 JM ✓ HW
 ND ✓
 TN ✓
 ND ✓
 DD ✓ 693.20
 NE ✓
 NE ✓
 DD ✓
 ND ✓
 DD ✓ HW
 BR ✓
 DD ✓ 478.80
 NE ✓
 ND ✓
 DD ✓ 1619.00
 NS ✓
 DD ✓
 NE ✓
 ND ✓
 NS ✓

2	Tailgate windscreen glass inner seal	1	\$30.00	50.00
3	Tailgate "70km/h" sticker	1	\$20.00	35.00
4	Tailgate "9pax" sticker	1	\$20.00	35.00
5	Rear bumper reverse sensor	1set	\$200.00	320.00
6	End panel joint sealant (outer)	1	\$30.00	20.00
7	End panel joint sealant (inner)	1	\$	20.00
8	RH taillamp panel joint sealant	1	\$	30.00
9	RH side panel joint sealant	1	\$30.00	80.00
Total:			\$	760.00

NECV
SC
NECV
NNX
NSX
NECV

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,000.00 (1200.00)
2	Spray painting on affected areas and panels	\$ 1,600.00 (800.00)
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 120.00 200.00
6	Remove and replace tailgate inner mechanism to new tailgate	\$ 80.00 220.00
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 60.00 120.00
8	Remove and replace exhaust silencer to assist repair	\$ 180.00
9	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 320.00
10	Remove and reinstall fuel tank, pipes and garnish to assist repair	\$ 80.00 180.00
Total:		\$ 5,020.00

NNX
NNX

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Spare Parts: \$ 9,567.58
Special Nett: \$ 760.00
Labour: \$ 5,020.00
Total Amount: \$ 15,347.58

Survey & Resurvey
20/5/2022
Total Man
134.5 hrs

Lump sum repair
Repair day 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____