

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 1 V.

21/6/22 PIP \$ 10561.08 informed hamzah (Red \$ 3191.80, 237-)

Date/Time, File Pass to?

1) 21/6 Marcus

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

(0561.08)

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
T: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0167/22

DATE : 05-MAY-2022

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)

TEL : 63954779/67143369

FAX : 63953768

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR SANTHANAM RAMKUMAR
ADDRESS : BLK 401 SERANGOON AVE 1
#05-11
S(550401)
TELEPHONE NO : 96934263

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SMX3217S
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2302531A
CHASSIS NO : SJNFEAJ11U1710628
MILEAGE : 76226 KM
DATE IN : 05/05/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 04/05/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
See
Take the 3rd party
23/5/22
7 days
26/5/22 10561.08

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMX3217S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER.	1800.00	✓ 1365.
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1500.00	✓ 1100.
3	ZZ/003	RENEW REVERSE SENSOR AND RESET.	110.00	✓ .
4	ZZ/004	R/I REVERSE CAMERA, FINISHER MOUNTING, RESET AND FUNCTION TEST.	190.00	✓ .
5	ZZ/005	RENEW REAR WINDSCREEN GLASS.	240.00	✓ .
6	ZZ/006	APPLY SEALANT TO TAIL GATE BACK DOOR.	100.00	✓ .
7	ZZ/007	PERFORM RUST PROOFING TO REAR PANEL.	120.00	✓ .
8	ZZ/008	RENEW REAR TAIL LAMP AND CHECK LIGHT SYSTEM.	48.00	✓ .
9	ZZ/009	SUPPLY REAR LICENCE PLATE.		
10	ZZ/10	RENEW REAR WINDSCREEN SOLAR FILM.	150.00	✓ .
TOTAL LABOUR CHARGES			4258.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX3217S

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1	SUNDRIES	X NPN		11	50.00 X
2	REAR LICENCE PLATE	/ RLP		BLW/ 4.5	60.00
3	TAIL GATE LAMP LH	X 26555-4EA6E	11 373.80	X	
4	TAIL GATE LAMP RH	X 26550-4EA5E	11 373.80	X	
5	REAR COMB LAMP LH	X 26555-4EA0A	11 412.10	X	
6	REAR COMB LAMP RH	/ 26550-4EA0A	CNA 412.10	P	
7	CARPET-LUGGAGE	X 84904-4EA0A	11 449.90	X	
8	CLIP TOP PLATE @ \$1.40 EACH	/ 01553-05323	11 11.20		
9	TRUNK TOP PLATE	X 84992-4EA0A	11 74.30	X	
10	EMBLEM REAR QASHQAI	/ 90892-4EA0A	11 101.90		
11	EMBLEM-REAR NISSAN	/ 90890-4EA0A	11 70.00		
12	STRIKER-TAIL GATE	X 90570-4EA0A	11 37.60	X	
13	TAIL GATE LOCK	X 90502-4EA0B	SU 205.50	X	
14	REAR W/SCREEN SEALANT	/ SEALANT - 4		11	80.00
15	REAR W/SCREEN MLDG	11 G2891-89926	- 244.30	X	
16	REAR W/SCREEN FASTENER	/ G2G16-89901	11 68.90		
17	REAR WINDSCREEN GLASS	/ 90300-4EA0D	11 1174.80		
18	TAIL GATE TOP HANDLE MLDG	X 90810-4ES0H	11 380.00	X	
19	TAIL GATE W/STRIP	X 90830-4EA0A	11 198.40	X	
20	TAIL GATE BACK DOOR	/ K0100-4EAAC	Bolgio 3636.60		
21	REAR PANEL	/ G9110-4EAMA	11 573.80		
22	REAR BUMPER REFLECTOR LH	X 26565-JJ90A	11 66.90	X	
23	REAR BUMPER REFLECTOR RH	X 26560-JJ90A	11 66.90	X	
24	SENSOR-REVERSE	/ SENSOR		shua	250.00
25	REAR BUMPER REINFORCEMENT	/ H5030-4EAMA	Bol 746.20		

c/w assembly

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX3217S

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
26 ENERGY ABSORBER REAR BUMPER	85090-4EA0B	168.10		
27 REAR BUMPER STAY LH	H5211-4EAMA	152.40		
28 REAR BUMPER STAY RH	H5210-4EAMA	152.40		
29 REAR BUMPER TOW HOOK COVER	85071-4EA0A	22.40		
30 REAR BUMPER SIDE BRKT LH	85221-4EA0A	42.00		
31 REAR BUMPER SIDE BRKT RH	85220-4EA0A	42.00		
32 REAR BUMPER RETAINER	79184-4EA0A	27.80		
33 CLIP REAR BUMPER @ \$8.60 EACH	85284-JD00A	86.00		
34 REAR BUMPER FASCIA	85022-4EA0H	946.50		
SUB TOTAL		11318.60	0.00	440.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		2263.72	0.00	0.00
GRAND TOTAL		9054.88	0.00	440.00
OVERALL TOTAL		9494.88		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMX3217S

TOTAL LABOUR CHARGES	4258.00
TOTAL SPARE PARTS CHARGES	9494.88

GRAND TOTAL	13752.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Attn: Marcus
17/6/2022

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0167/22

DATE : 05-MAY-2022

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)

TEL : 63954779/67143369

FAX : 63953768

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR SANTHANAM RAMKUMAR
ADDRESS : BLK 401 SERANGOON AVE 1
#05-11
S(550401)
TELEPHONE NO : 96934263

7 day p.

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SMX3217S
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2302531A
CHASSIS NO : SJNFEAJ11U1710628
MILEAGE : 76757 KM
DATE IN : 05/05/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 04/05/2022

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMX3217S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER.	1800.00	1365.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1500.00	1100.00
3	ZZ/003	RENEW REVERSE SENSOR AND RESET.	110.00	110.00
4	ZZ/004	R/I REVERSE CAMERA, FINISHER MOUNTING, RESET AND FUNCTION TEST.	190.00	190.00
5	ZZ/005	RENEW REAR WINDSCREEN GLASS.	240.00	240.00
6	ZZ/006	APPLY SEALANT TO TAIL GATE BACK DOOR.	100.00	100.00
7	ZZ/007	PERFORM RUST PROOFING TO REAR PANEL.	120.00	120.00
8	ZZ/008	RENEW REAR TAIL LAMP AND CHECK LIGHT SYSTEM.	48.00	48.00
9	ZZ/009	SUPPLY REAR LICENCE PLATE.		
10	ZZ/10	RENEW REAR WINDSCREEN SOLAR FILM.	150.00	150.00
TOTAL LABOUR CHARGES			4258.00	3423.00

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX3217S

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMA
1	TAIL GATE BACK DOOR	K0100-HVOMB	3636.60		OK
2	REAR W/SCREEN FASTENER	G2G16-89900	68.90		OK
3	CLIP TOP PLATE @ \$1.40 EACH	01553-05933	11.20		OK
4	SUNDRIES	NPN			50.00 X
5	REAR LICENCE PLATE	RLP			60.00 OK
6	TAIL GATE LAMP LH	26555-4EA6E	373.80		X
7	TAIL GATE LAMP RH	26550-4EA5E	373.80		X
8	REAR COMB LAMP LH	26555-4EA0A	412.10		X
9	REAR COMB LAMP RH	26550-4EA0A	412.10		OK
10	CARPET-LUGGAGE	84904-4EA0A	449.90		X
11	TRUNK TOP PLATE	84992-4EA0A	74.30		X
12	EMBLEM REAR QASHQAI	90892-4EA0A	101.90		OK
13	EMBLEM-REAR NISSAN	90890-4EA0A	70.00		OK
14	STRIKER-TAIL GATE	90570-4EA0A	37.60		X
15	TAIL GATE LOCK	90502-4EA0B	205.50		X
16	REAR W/SCREEN SEALANT	SEALANT - 4			80.00 OK
17	REAR W/SCREEN MLDG	G2891-89926	244.30		X
18	REAR WINDSCREEN GLASS	90300-4EA0D	1174.80		OK
19	TAIL GATE TOP HANDLE MLDG	90810-4ES0H	380.00		X
20	TAIL GATE W/STRIP	90830-4EA0A	198.40		X
21	REAR PANEL	G9110-4EAMA	573.80		OK
22	REAR BUMPER REFLECTOR LH	26565-JJ90A	66.90		X
23	REAR BUMPER REFLECTOR RH	26560-JJ90A	66.90		X
24	SENSOR-REVERSE	SENSOR			250.00 OK
25	REAR BUMPER REINFORCEMENT	H5030-4EAMA	746.20		OK

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX3217S

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMA
26	ENERGY ABSORBER REAR BUMPER	85090-4EA0B	168.10		OK
27	REAR BUMPER STAY LH	H5211-4EAMA	152.40		OK
28	REAR BUMPER STAY RH	H5210-4EAMA	152.40		OK
29	REAR BUMPER TOW HOOK COVER	85071-4EA0A	22.40		OK
30	REAR BUMPER SIDE BRKT LH	85221-4EA0A	42.00		OK
31	REAR BUMPER SIDE BRKT RH	85220-4EA0A	42.00		OK
32	REAR BUMPER RETAINER	79184-4EA0A	27.80		OK
33	CLIP REAR BUMPER @ \$8.60 EACH	85284-JD00A	86.00		OK
34	REAR BUMPER FASCIA	85022-4EA0H	946.50		OK
SUB TOTAL			8435.10	0.00	390.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1687.02	0.00	0.00
GRAND TOTAL			6748.08	0.00	390.00
OVERALL TOTAL			7138.08		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMX3217S

NETT ITEM	8435.10
LESS 20.00%)	-1687.02
NETT AMOUNT	6748.08

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	390.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	390.00

TOTAL LABOUR CHARGES	3423.00
TOTAL SPARE PARTS CHARGES	7138.08

TOTAL CHARGES	10561.08
ADD 7 % GST	739.28

GRAND TOTAL	11300.36
-------------	----------
