

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 48992400W

Vehicle Number: SDA3180R

Vehicle Model : BMW 520D M Sport Auto

Manufacturing Year : 2017

Chassis : WBAJC32030G865110

TP Budget Direct.

Veron

S/N.	Item Description	Amount
1	Rear Boot <i>Dented.</i>	\$ 2,666.74
2	Rear Boot Hinge x 2 pcs <i>New</i>	\$ 569.93
3	"520d" Emblem <i>3 New</i>	\$ 122.40
4	BMW Logo <i>3 New</i>	\$ 127.50
5	Rear Boot Trimboard <i>3 New</i>	\$ 392.42
6	Rear Boot Trimboard Clip x 1 set <i>3 New</i>	\$ 50.00
7	Rear Boot Lock <i>3 New</i>	\$ 523.24
8	Rear Boot Catch <i>3 New</i>	\$ 163.59
10	Rear Boot Lamp (RH) <i>New</i>	\$ 617.70
11	Rear Boot Weatherstrip <i>New</i>	\$ 342.90
12	Rear Boot Truck Smart Opener Control Module <i>New</i>	\$ 795.76
13	Taillamp (RH) <i>Cracked</i>	\$ 880.10
14	Rear Bumper <i>Distorted.</i>	\$ 2,698.50
15	Rear Bumper Lower Portion <i>Distorted.</i>	\$ 539.70
16	Rear Bumper Lower Heat Shield Undercover <i>cracked</i>	\$ 431.80
17	Rear Bumper Reflector (RH) <i>cracked.</i>	\$ 82.24
18	Rear Bumper Clip x 1 set <i>New</i>	\$ 50.00
19	Rear Bumper Side Retainer (RH) <i>Cracked.</i>	\$ 542.30
20	Rear Bumper Centre Retainer <i>cracked</i>	\$ 287.00
21	Rear Bumper Reinforcement <i>Dented</i>	\$ 1,589.50
22	Rear Bumper Exhaust Support <i>Cracked New</i>	\$ 614.23
23	Towing Cover <i>Dented.</i>	\$ 65.80
24	End Panel <i>Dented.</i>	\$ 844.27
25	End Panel Top Garnish <i>cracked</i>	\$ 285.60
26	Rear Exhaust <i>Not rec</i>	\$ 1,942.58
27	Rear Exhaust Heat Shield (Centre) <i>New</i>	\$ 442.22
28	Rear Exhaust Heat Shield (RH) <i>cracked</i>	\$ 309.88
29	Rear Exhaust Mounting (RH) <i>New</i>	\$ 116.84
30	Reverse Sensor Holder x 3 pcs <i>New</i>	\$ 637.36
31	Reverse Sensor x 3 pcs <i>1 piece dented</i>	\$ 771.00
32	Battery Overload Protection Pyrofuse <i>Activated.</i>	\$ 173.11
33	Front Seatbelt (RH) <i>Activated</i>	\$ 919.00
34	Top Roof Airbag x 2 pcs <i>Activated</i>	\$ 4,637.60

2380.

185.

1600(SN).

290.

125.

967

90.

257

		\$	1,670.50
35	Airbag Control Unit Activated	\$	
36	Top Roof Lining crumpled.	\$	3,189.22
37	Top Roof Lining Clip x 1 set new	\$	50.00
	18028.70		
	less 10% : 16225.83		
	Total :	\$	30,142.53
	Less 10% :	\$	3,014.25
	Amount :	\$	27,128.28

S/N	Special Nett Item	Amount (\$)
1	End Panel Sealant <i>wec</i>	\$ 50.00
	<i>SO</i>	
	Amount :	\$ 50.00

Labour	Amount (\$)
To towing	\$ 120.00
To use computer diagnostic and resetting	\$ 380.00
To check rear electrical wiring system	\$ 180.00
To remove and reinstall rear bumper sensors	\$ 80.00
To remove and reinstall rear tyre compartment interior trims, garnishes etc to facilitate repair	\$ 180.00
To remove & reinstall top roof trims & garnishes to facilitate repair	\$ 480.00
To remove & reinstall airbags and seatbelt	\$ 800.00
To transfer rear boot components from old boot to new boot	\$ 120.00
To remove & install rear exhaust	\$ 350.00
To apply anti-rusting coating on new and affected areas	\$ 200.00
Labour to remove, cut, change & panel beating	\$ 2,400.00
To putty and respray affected areas	\$ 1,800.00
Labour Total :	\$ 7,090.00
Total (Parts & Labour)	\$ 34,268.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company