

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Yi Guang@Hagel Tan Abdullah

Date: 28 Jun 2022

Preliminary Advice

Insured Vehicle No	: SJZ5052L	Accident Date	: 17/05/2022
TP Vehicle No	: SMK4593S	Assignment Date	: 20/05/2022
Make	: HYUNDAI SANTA FE	Est. Duration of Repair	: 06
Date of Inspection	: 23/05/2022		
Inspection At	: AH LIM MOTOR COMPANY		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,947.00
Revised Amount	:S\$	6,095.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,095.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a "Without Prejudice" basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.