

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 24 May 2022

Preliminary Advice

Vehicle No	: SMU936K	Accident Date	: 22/04/2022
Make	: VOLKSWAGEN	Policy No.	:
	BEETLE		DMPCSNW00176202101
	CABRIOLET		
Assignment Date	: 20/05/2022	Excess	: S\$500.00
Date of Inspection	: 20/05/2022	Est. Duration of Repair	: 3
Inspection At	: KIRALY AUTOMOBILE PRIVATE LIMITED (HQ) 8 KAKI BUKIT AVENUE 4, #06-43, PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,240.00
Revised Amount	:S\$	1,607.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,607.80

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 90,000.00

COE / PARF Rebate	:S\$ 40,708.00
Salvage Value	:S\$
Margin for Repair	:S\$ 49,292.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :
Please note that this vehicle already done for repair at the time of inspection.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.