

Vehicle Damage Assessment Report for [SDN6895Z]

Estimate Created: 21/05/2022 10:01 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 02/06/2022 23:46 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Elantra
Engine Type			
License Plate Number	SDN6895Z	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final Review: Concluded the cost of repair at lump sum \$4800.00 with 4 days for repair

Insurlogic 1 (02/06/2022 23:46)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
BOOTLID		1	1782.00	-20.00 %	1,425.60
BOOTLID INNER LOCK		1	145.00	-20.00 %	116.00
BOOTLID WEATHERSTRIP		1	166.00	-20.00 %	132.80
REAR BUMPER		1	498.00	-20.00 %	398.40
REAR BUMPER BEAM		1	341.00	-20.00 %	272.80
REAR BUMPER LOWER GARNISH		1	450.00	-20.00 %	360.00
REAR BUMPER SIDE RETAINERS		1	130.00	-20.00 %	104.00
REAR BUMPER CLIPS		1	45.00	-20.00 %	36.00
TAIL LAMP		1	580.50	-20.00 %	464.40
END PANEL		1	585.90	-20.00 %	468.72
REAR BUZZLE SENSOR		1	220.00	-20.00 %	176.00
END PANEL TOP GARNISH		1	199.00	-20.00 %	159.20
REVERSE SENSOR		1	200.00	0.00 %	200.00
END PANEL SEALANT		1	50.00	0.00 %	50.00

Parts Subtotal 4,363.92

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRE	RnR	20.00	0.00 %	20.00
REPLACE REVERSE SENSOR	RnR	50.00	0.00 %	50.00
TRANSFER BOOTLID MECHNISUM	RnR	60.00	0.00 %	60.00
REMOVE AND REFIX CUSHION UPHOLSTRY	RnR	80.00	0.00 %	80.00
RUST PROOFING	RnR	60.00	0.00 %	60.00
REPLACE REAR BOOTLID	RnR	100.00	0.00 %	100.00
REPLACE REAR BUMPER	RnR	100.00	0.00 %	100.00
REPLACE END PANEL	RnR	400.00	0.00 %	400.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TAILGATE	Full spray	200.00	0.00 %	200.00
REAR BUMPER	Full spray	200.00	0.00 %	200.00
END PANEL	Full spray	200.00	0.00 %	200.00

REAR FLOOR PANEL	Full spray	200.00	0.00 %	200.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	870.00
			Paint Labor Subtotal	800.00
			Labor Subtotal	1,670.00

Summary

Repair Cost	6,033.92
Discount(20 %)	(1,233.92)
	4,800.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,800.00