ASS. REC. BY: Tayph REF: CT	
	SIGNMENT
From: Date:	Veh No: SH7448D. Yr Regn: 2019, July.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / Prime Mover /
OD (T) / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hymder long, c.c 1580
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 726724 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KMHC851 CV KUE 164401
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Otil / S/Rim / STD A/Rim or
	Tyre Size: F: 45 17 145
(Policy Condition)	R: NA
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or wather.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal ϵ mm R/Bal ϵ
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs days Res.: Yes or No	D.O.A. D.O.I. 11/5/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Comput Lynn.
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OU Date: Person Contacted: Vehicle: IN/OU	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Pate / Time / Addit / Instable()	
1	1
· · · · · · · · · · · · · · · · · · ·	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$)s+Rssi
	Interview (\$
Repros Format :	: Tech Inve (%
Lump Sum / LB.J: (%)	: Weel:end (%
1.	TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

12.05.2022

MODEL:

Hyundai loniq

VEHICLE NO .: SH 7448D

LKK-

INSURANCE: CHINA TAIPING

CPP)

MVA: LIMTS

PART NO.					· -	-1141 1 3	
ANTINO,	DESCRIPTION	QTY	U	NIT PRICE		AMOUNT	
	Rear Bumper	1	M. Physical a		\$	The second secon	10
	Rear Bumper Reinforcement	1			\$	394.80	
	Rear Bumper Reinforcement Bracket LH/RH	2	\$	138.10	\$		
	Rear Bumper Centre Moulding	1	1		Ι΄.	_, _,	15
	Rear Bumper Lower Centre Moulding	1			\$	451.25	- I.
	Rear Bumper Cover Clips	10	\$	2.20	\$	155.00	10.
	Rear Bumper Tow Cover	1	Ψ	2.20	\$	22.00	
	Rear Bumper Reflector LH / RH	2	\$	44.45	\$	98.80	1
	Rear Foglamp	1	Þ	41.15	\$	82.90	
		'			\$	201.50	*
	SUB TOTAL					2012	
	LESS 20%				\$	2,141.85	7
	DISCOUNTED TOTAL				\$	428.37	
•		,			\$	1,713.48	
	Rear Bumper Mat						
	Reverse Sensors	1			\$	50.00	nei
	Rear No.Plate With Trim Cover	1			\$	180.00	mi-
	Rear Fender Adv.Sticker RH/LH	1			\$	55.00	are /
	The state of the first	2	\$	100.00	\$	200.00	101
	NETT TOTAL				_		
				-	\$	485.00	
	SPARE PARTS TOTAL			-	•		
	Labour Charge			-	\$	2,198.48	
	Panel Beating						
	Spray Painting Charge	İ			\$	400.00	350
	Remove/Refix Reverse Sensor	-			\$	300.00	250
	Service Serisor	l			\$	120.00	30
						120.00	70
	TOTAL LABOUR			-	_		
				-	\$	820.00	
	ESTIMATE TOTAL			-	\$	3 040 40	
is is an initial e	stimate based on a visual income:			-	Ψ	3,018.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanskri 92495749 up, 12/5/72 e 315p-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pleaser before peint tarphic Wharb com



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 12.05.2022 14:30

Page: 1

ARC Repair TP(CLSO)1 am:

JOB CARD Sales Order: 4207139

JC NO.305515830

OMER

IS

COMFORT TRANSPORTATION PTE LTD

7010045 OMER NO

383 SIN MING DRIVE ESS

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P)

DUNT CARD NO.

REGN NO.: SH 7448D	MILEAGE
MAKE: HYUNDA I	FUEL EF .
MODEL IONIQ(G2) 12	DATE/TIME IN 05.2022 12:25
YR OF MANU. 02.07.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164401	COMPLETION DATE/TIME:


JOB DESCRIPTION

ccident Date: 12.05.2022

ATURE: 3P 12.05.2022

/NO 00010 LABOR CODE

DESCRIPTION PANEL BEATING-SH 7448D-TP



	,		
			REAR
*			

KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

LIMTS

Vehicle No.:

Exit Pass

SH 7448D

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

SH 7448D

To be kept by Security Guard