

REPAIR ESTIMATEDATE: 12.05.2022MODEL: Hyundai IoniqVEHICLE NO.: SH 7448DINSURANCE: CHINA TAIPINGMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ ✓ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH	2	\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding	1		\$ ✓ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ ✓ 22.00
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper Reflector LH / RH	2	\$ 41.15	\$ 82.90
	Rear Foglamp	1		\$ 201.50
				\$ 2,141.85
				\$ 428.37
				\$ 1,713.48
				\$ ✓ 50.00
				\$ 180.00
				\$ ✓ 55.00
				\$ 200.00
				\$ 485.00
				\$ 2,198.48
				\$ 400.00
				\$ 300.00
				\$ 120.00
				\$ 820.00
				\$ 3,018.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphir 97495749  
up, 12/5/22 @ 3:15pm

2 days  
p/p Resurvey before paint  
tanphir@lkhauto.com

2 days