

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305515582
 REGN NO : SHC3950C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.04.2016
 DATE/TIME IN : 09.05.2022 23:00
 ACCIDENT DATE : 09.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00 442.40 <i>Ry</i>
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00 17.60 <i>net</i>
0003	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00- 50.00 <i>x m</i> 236.20
0004	04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	214.20	20.00 171.36 <i>cut</i> 188.96

SUB-TOTAL : 681.36

JOB NATURE

0000 PB	PANEL BEATING	500.00	280
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30 810

SUB-TOTAL : 1,150.00

TOTAL : 1,831.36

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfilin 97495749
'wp' 11/5/22 @ 330pm
2 days
1/5 Resurvey after repair
tanfilin@lkkauto.com

998.96
1/5 800
2 days
#