

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 16/05/2022

Estimated repair cost for vehicle no : SJJ3410J DAIHATSU MATERIA 1.5L AUTO ABS AIRBAG 2WD

18/05/2022

TP ALG.
Asher.

CHASSIS: JDAM402S001012801 (2008)

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT DOOR <i>Distorted</i>	\$1,259.00	\$1,259.00 ✓ <i>895</i>
2	2	RH FRONT DOOR HINGE <i>but</i>	\$89.00	\$178.00 ✓
3	1	RH FRONT DOOR CHECKER <i>ren</i>	\$65.00	\$65.00 ✗
4	1	RH FRONT DOOR WEATHER STRIPE <i>at</i>	\$289.00	\$289.00 ✓
5	1	RH FRONT DOOR GLASS <i>Shattered</i>	\$452.00	\$452.00 ✓
6	1	RH FRONT DOOR GLASS OUTER MOULDING <i>Red</i>	\$127.00	\$127.00 ✓
7	1	RH FRONT DOOR GLASS INNER RUBBER <i>ren</i>	\$145.00	\$145.00 ✗
8	1	RH FRONT DOOR GLASS OUTER GARNISH <i>ren</i>	\$65.00	\$65.00 ✗
9	1	RH FRONT DOOR OUTER HANDLER <i>ren</i>	\$112.00	\$112.00 ✗
10	1	RH FRONT DOOR LOCK <i>Damaged</i>	\$108.00	\$108.00 ✓
11	1	RH FRONT DOOR INNER TRIM BOARD <i>crackd</i>	\$548.00	\$548.00 ✓ <i>395</i>
12	1	RH FRONT DOOR POWER WINDOW MOTOR <i>ren</i>	\$658.00	\$658.00 ✗
13	1	RH FRONT DOOR POWER WINDOW MOTOR GEAR <i>Damaged</i>	\$445.00	\$445.00 ✓
14	1	RH FRONT DOOR BLACK STICKER <i>ren</i>	\$78.00	\$78.00 ✓
15	1	RH FRONT DOOR WIRE HARNESS <i>Whole ren</i>	\$848.00	\$848.00 ✗
16	1	RH FRONT DOOR POWER WINDOW SWITCH WITH HOLDER <i>crackd</i>	\$287.00	\$287.00 ✓
17	1	RH FRONT DOOR ARM REST CUSHION <i>ren</i>	\$69.00	\$69.00 ✗
18	1	RH FRONT DOOR MIRROR <i>crackd</i>	\$658.00	\$658.00 ✓
19	1	RH FRONT DOOR MIRROR COVER <i>crackd</i>	\$98.00	\$98.00 ✗
20	1	RH FRONT DOOR MIRROR INNER GARNISH COVER <i>crackd</i>	\$23.00	\$23.00 ✓
21	1	RH FRONT DOOR PILLAR PANEL (OUTER) <i>ren</i>	\$783.00	\$783.00 ✗
22	1	RH FRONT DOOR CENTER PILLAR (OUTER) <i>Dented</i>	\$882.00	\$882.00 ✓
23	1	RH FRONT DOOR CENTER PILLAR INNER GARNISH <i>ren</i>	\$116.20	\$116.20 ✗
24	1	RH FRONT DOOR PILLAR LOWER GARNISH <i>Red</i>	\$98.00	\$98.00 ✓
25	1	RH FRONT DASHBOARD AIR VENT <i>ren</i>	\$83.00	\$83.00 ✗

SJJ3410J DAIHATSU MATERIA

26	1	RH FRONT STEP PANEL GARNISH <i>Defect</i>	\$78.00	\$78.00 ✓
27	1	RH ROCKER PANEL (OUTER) <i>Defect</i>	\$554.00	\$554.00 ✓

5547
4714.95

TOTAL :	\$9,106.20
LESS 15 %	\$1,365.93
SUB-TOTAL :	\$7,740.27

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT DOOR INNER SPEAKER <i>Could</i>	\$350.00	\$350.00 <i>120</i>
2	1	RH FRONT DOOR GLASS SOLAR FILM <i>Nec</i>	\$180.00	\$180.00 <i>150</i>
3	1	RH FRONT DOOR INNER TRIM BOARD CLIPS <i>Nec</i>	\$60.00	\$60.00 <i>30</i>
4	1	RH ROCKER PANEL GARNISH <i>Defect</i>	\$450.00	\$450.00 ✓
5	1	RH ROCKER PANEL GARNISH CLIPS <i>Nec</i>	\$60.00	\$60.00 <i>30</i>

780

TOTAL: **\$1,100.00**

TOTAL PARTS: **\$8,840.27**

Labour charges

1	LABOUR FOR PANEL BEATING	<i>1780</i>	\$1,800.00 <i>700</i>
2	LABOUR FOR SPRAYPAINTING		\$1,200.00 <i>750</i>
3	WIRING CHECK		\$80.00 <i>30</i>
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS		\$200.00 <i>60</i>
5	LABOUR FOR REMOVE & REFIX RH FRONT INNER GARNISH / CARPET / UPHOLSTERY / ROOF LINING		\$300.00 <i>80</i>
6	LABOUR FOR REMOVE & TRANSFER ALL REAR DOOR FITTING		\$300.00 <i>80</i>
7	LABOUR FOR CLEAN & VACCUM SHATTERED GLASS INCLUDE REMOVE & REFIX FRONT DASHBOARD / RH AIR CON AIR VENT		\$300.00 <i>80</i>

Subtotal :- **\$4,180.00**

Total:- **\$13,020.27**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

total 7274.95
L/S: 5.8K
Adrian L
18/05/22
06 Pays.
5.8K