



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2022
User ID : PohSuan
Section A - Accident Details

Registration Number	SHB5798T
Case Reference Number	TAX/05/22/2037
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG HIN WOO
Type of Accident	Side Swipe
Accident Date and Time	13/5/2022 10:40 AM
Accident Reported Date and Time	13/5/2022 4:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114939
Special Instruction to ARC, if any	TP/ LEFT PORTION
Prepared Date and Time	14/5/2022 8:28 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$500.00
Total Spray Cost	\$2,232.00	\$750.00
Total Spare Part Cost	\$10,113.12	\$746.34
Total Other Cost	\$740.00	\$200.00
TOTAL COST	\$14,099.12	\$2,196.34
Lump Sum Total	\$14,100.00	\$2,200.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	17/05/2022 5:07 PM	17/05/2022 2:34 PM
Signature		
Remarks	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2206-0002	Invoice Number	
Quotation Date	01.06.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$500.00
Total Labour	\$1,014.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FUEL LID COVER	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,232.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$740.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2022

User ID : PohSuan

	52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
	52592470 40	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given	X
	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	X
	52566479 00	FILLER, RR BUMPER , LH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	R
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	81591470 10	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
	67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given	X
		STICKER STRIDES TAXI (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
	61312470 40	PILLAR, CENTER BODY, OUTER LH	0.00	\$313.40	0.00	\$0.00	Replace	Not Given	X
	67004472 10	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,243.90	25.00	\$932.93	Replace	Replace	✓
	68760201 22	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X
	68780520 31	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given	X
	85710471 50	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Check	X
	69804470 20	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$200.70	0.00	\$0.00	Replace	Check	X
	61018470 10	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	0.00	\$279.20	0.00	\$0.00	Replace	Not Given	X
	68630470 50	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X
	67872470 51	WEATHERSTRIP, REAR DOOR LH	0.00	\$174.40	0.00	\$0.00	Replace	Check	X
	69060522 80	DOOR LOCK REAR , LH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given	X
	67836330 30	DOOR REAR LOCK COVER	0.00	\$8.90	0.00	\$0.00	Replace	Not Given	X
	75740470 40	MOULDING ASSY, REAR DOOR BELT, LH	0.00	\$109.80	0.00	\$0.00	Replace	Not Given	X
	82154472 50	WIRE, REAR DOOR, LH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given	X
	861600R1 40	REAR DOOR SPEAKER ASSY, RADIO RH & LH	0.00	\$985.70	0.00	\$0.00	Replace	Not Given	X
	61602471 60	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
	65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X
	65638470 60	LINER, REAR FENDER , LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair	R
	43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42450760 20	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$610.20	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2022

User ID : PohSuan

		77350470 50	LID ASSY, FUEL FILLER OPENING	0.00	\$164.10	0.00	\$0.00	Replace	Not Given
			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
		75860479 00	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
Total					\$15,678.34		\$932.93		

X
X
R

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	932.93	
	-20%	
	746.34	L/S \$2,200/-
+	500.00	
+	950.00	
	2,196.34	