

SMN1115T

TPA19

Skoda Karoq

Xiao Tang.

TMBKR7NUSK5034167

Rear Number Plate	$\left. \begin{matrix} 2 \\ \text{HP} \\ \text{m} \end{matrix} \right\}$	30(SN) +
Rear Number Plate Holder		30(SN) +
Rear Bumper	Deformed	1485 1305
Rear Bumper Clips	m	30(SN) ✓
Rear Bumper Side Holder x 02	$\begin{matrix} 14 \\ \text{m} \end{matrix}$	$83 \times 2 = 166$ +
Rear Bumper Reinforcement	Dented	850 ✓
Rear Bumper Centre Guide	Curled	185 ✓
Rear Bumper Reflector x 02	$\begin{matrix} 14 \\ \text{m} \end{matrix}$	$115 \times 2 = 230$ +
Rear Bumper Side x 02	Rejis	$255 \times 2 = 510$ + 510.
Reverse Sensor x 04	2 pieces dmg	$255 \times 4 = 1020$ ✓
Reverse Sensor Holder x 04	m	$25 \times 4 = 100$ ✓
Rear End Panel	Rejis	980 X.
Rear End Panel Top Garnish	$\begin{matrix} 14 \\ \text{m} \end{matrix}$	285 X
Rear End Panel Top Garnish Clips	$\begin{matrix} 14 \\ \text{m} \end{matrix}$	10(SN) X

SMN1115T.

Rear End Panel Sealant	NA	60(SN) +
Taillamp x 02	RH and L	550 x 2 = 1100 550
Tailgate	Dented	2500 2295
Tailgate Lock	Dented	290 ✓
Tailgate Weatherstripe	NA	295 +
Tailgate Reflector x 02	NA	500 x 2 = 1000 +
Tailgate Inner Trim Board	2 NA	458 +
Tailgate Inner Trim Board Clips		30(SN) +
Tailgate G(s) Sealant	2 NA	60(SN) +
Tailgate G(s) Moulding	2 NA	185 +
Tailgate Lock Switch c/w Camera	RHD	680 ✓
Skoda Logo		95 ✓
Skoda Wording	NA	80 ✓
Karog Wording		80 ✓
		6820 S.N: 30
		6138

SMN1115T.

Panel Beating

~~1000~~ 600

Spray Painting.

~~1000~~ 600

Wiring.

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To spray tuff coat

~~150~~ 40

To remove rear camera.

~~100~~ 50

To remove rear video recorder

~~100~~ 50

To remove upholstery. 1660

~~150~~ 40

To transfer tailgate fittings

~~150~~ 80

To remove tailgate glass

~~180~~ 120

total: 7828

L/S: 6.2K

0.5 Days

6.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: