

see OIR

SK

AM WE3  
RTS

### Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-09, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : SGV 3737P  
Made : Volkswagen  
Model : Jetta GP  
Chassis No : \_\_\_\_\_

#### \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bootlid	1	\$ 2,080.80	\$ 1875 ✓ 2,080.80
2	Rear Bootlid Emblem	1	\$ 133.83	\$ 92 ✓ 133.83
3	Rear Bootlid Hinge RH	1	\$ 188.78	\$ 188.78
4	Rear Bootlid Hinge LH	1	\$ 188.78	\$ 188.78
5	Rear Bootlid Reflector Lamp RH	1	\$ 320.99	\$ 320.99
6	Rear Bootlid Reflector Lamp LH	1	\$ 320.99	\$ 320.99
7	Rear Bootlid Lock	1	\$ 233.89	\$ 233.89
8	Rear Bootlid Weatherstrip	1	\$ 269.89	\$ 269.89
9	Rear Taillamp Assembly RH	1	\$ 420.83	\$ 420.83
10	Rear Taillamp Assembly LH	1	\$ 420.83	\$ 382 ✓ 420.83
11	Rear Taillamp Lower Bracket RH	1	\$ 83.43	\$ 83.43
12	Rear Taillamp Lower Bracket LH	1	\$ 83.43	\$ 83.43 ✓
13	Rear Taillamp Panel RH	1	\$ 485.80	\$ 485.80
14	Rear Taillamp Panel LH	1	\$ 485.80	\$ 485.80
15	Rear Bumper	1	\$ 1,355.34	\$ 1,355.34 ✓
16	Rear Bumper Sponge	1	\$ 143.61	\$ 143.61
17	Rear Bumper Reinforcement	1	\$ 650.77	\$ 650.77
18	Rear Bumper Bracket RH	1	\$ 91.28	\$ 91.28
19	Rear Bumper Bracket LH	1	\$ 91.28	\$ 91.28 ✓
20	Rear Bumper Guide RH	1	\$ 91.28	\$ 91.28
21	Rear Bumper Guide LH	1	\$ 91.28	\$ 91.28
22	Rear Bumper Attachment Strip	1	\$ 84.92	\$ 84.92
23	Rear Bumper Lower Spoiler	1	\$ 502.15	\$ 502.15
24	Rear Bumper Reflector RH	1	\$ 87.43	\$ 87.43
25	Rear Bumper Reflector LH	1	\$ 87.43	\$ 87.43 ✓
26	Rear End Panel	1	\$ 1,206.00	\$ 1,206.00 ✓
27	Rear End Panel Top Garnish	1	\$ 145.75	\$ 145.75
28	Rear Fender LH	1	\$ 1,858.05	\$ 1615 ✓ 1,858.05
29	Rear Fender Air Vent LH	1	\$ 65.15	\$ 65.15 ✓
30	Rear Fender Inner Trim LH	1	\$ 396.65	\$ 396.65
31	Rear Fender Inner Shield LH	1	\$ 302.15	\$ 302.15
Parts Sub Total :				\$ 12,968.59
Discount 10% :				\$ 1,296.86
<b>PARTS TOTAL :</b>				<b>\$ 11,671.73</b>

BTU  
NECV  
NDX  
NDX  
NDX  
NDX  
BRV ✓  
NDX  
BRV ✓  
NDX  
BRV ✓  
NSX  
NDX  
NDX  
BRV ✓  
NDX  
NDX  
BRV ✓  
DDV ✓  
NDX  
DDV ✓  
BRV ✓  
NDX

6852.63  
-10%  
6167.36

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ <del>50.00</del>	NNX
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ <del>50.00</del> ✓ 30.00	NECV
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ <del>50.00</del>	NSX
4	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ <del>50.00</del>	} NNX
5	Rear Fender Inner Shield Clips - Set	1	\$ 40.00	\$ <del>40.00</del>	
6	Rear Fender Inner Trim Clips - Set	1	\$ 80.00	\$ <del>80.00</del>	
7	Rear Bootlid Inner Trim Clips - Set	1	\$ 50.00	\$ <del>50.00</del>	} NNX
8	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ <del>150.00</del>	
9	Rear Bootlid Sealant	1	\$ 150.00	\$ <del>150.00</del> ✓ 30.00	NECV
10	Rear End Panel Sealant	1	\$ 150.00	\$ <del>150.00</del> ✓ 30.00	NECV
11	Rear Fender LH Sealant	1	\$ 150.00	\$ <del>150.00</del> ✓ 30.00	NECV
12	Rear Bootlid Top Spoiler	1	\$ 800.00	\$ <del>800.00</del>	NSX
13	Rear Bumper Reverse Sensor - Set	1	\$ 450.00	\$ <del>450.00</del> ✓ 200.00	SCV
14	Rear Bootlid Reverse Camera	1	\$ 750.00	\$ <del>750.00</del>	NDX
			<b>320</b>	<b>SPECIAL NETT TOTAL :</b>	<b>\$ 2,970.00</b>

Nos.	LABOUR	S\$		
1	To Panel Beat, Remove & Refix Parts	\$ <del>1600.00</del> 1,600.00	} NNX	
2	To Spray Paint Affected Areas	\$ <del>800.00</del> 1,400.00		
3	Wiring & Bulb Check	\$ 100.00		
4	To Remove & Refix Rear Windscreen Glass	\$ <del>150.00</del>	} NNX	
5	To Transfer Rear Bootlid Mechanism	\$ <del>150.00</del> 80.00		
6	To Remove & Refix Rear Reverse Camera	\$ <del>150.00</del>	} NNX	
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ <del>120.00</del> 60.00		
8	To Remove & Refix Rear Exhaust Pipe	\$ <del>150.00</del>	} NNX	
9	To apply anti rust on affected parts	\$ <del>150.00</del>		
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ <del>150.00</del>		
11	To Conduct Water Leak Test	\$ <del>100.00</del>		
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ <del>580.00</del>		
		<b>1940</b>	<b>LABOUR TOTAL :</b>	<b>\$ 4,800.00</b>

Survey & Resurvey  
 23/5/2022  
 Train Lin  
 145 hrs  
 Lump sum repair  
 Repair days 9

PARTS TOTAL : \$ 11,671.73  
 SPECIAL NETT TOTAL : \$ 2,970.00  
 LABOUR TOTAL : \$ 4,800.00  
**GRAND TOTAL : \$ 19,441.73**

8427.36

L/S - 6741.88  
 = 6750

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: