

Not Notified  
Resuming B & paint

**Trans-cab Auto Services Pte Ltd**  
No. 2 Ang Mo Kio Street 63 Singapore 569111  
Tel No. : 6287 6666 Fax No. : 6257 1330  
CO./GST Reg. No. 201019626G  
**SHC5301M**

AAD2205-

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

20 MAY 2022

**SHC5301M**  
JTDKB3FU903091198  
200303878K  
TOYOTA  
PRIUS GEN 4  
19/05/2022  
**SMK9851P/CHINA**  
14/07/2020

	PART	LIST		
1	COVER, REAR BUMPER	RM/CN	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	R	332.70	X
1	GUARD, REAR BUMPER, CENTER	RM	374.50	✓
1	SEAL, REAR BUMPER SIDE, RH	SM	118.30	X
1	RETAINER, REAR BUMPER SIDE, RH	DI	132.60	✓
1	COVER, REAR BUMPER, LOWER	PL	22.00	X
1	COVER, DECK TRIM, REAR	SM	126.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK	R	651.00	X
1	REFLECTOR ASSY, REFLEX, RH	SM	39.00	X
1	LAMP ASSY, REAR, RH	RM / CN	293.60	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	SM	339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	CN	261.00	✓
1	PANEL SUB-ASSY, BACK DOOR	R	1,147.80	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	RM	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	RM	54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	RM	47.90	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	CN	913.60	✓
1	BOARD ASSY, BACK DOOR TRIM	SM	259.20	X
1	WEATHERSTRIP, BACK DOOR	SM	372.30	X
1	STAY ASSY, BACK DOOR, LH	SM	242.50	X
1	STAY ASSY, BACK DOOR, RH	SM	242.50	X
1	HINGE ASSY, BACK DOOR, LH	R	61.00	X
1	HINGE ASSY, BACK DOOR, RH	R	61.00	X
<b>TOTAL</b>		<b>\$</b>	<b>6,633.60</b>	
<b>25%</b>		<b>\$</b>	<b>1,658.40</b>	
		<b>\$</b>	<b>4,975.20</b>	

Special Nett

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G

AAD2205-

**SHCS301M**

1 REAR BUMPER SIDE CLIP	\$	na	60.00	✓
1 BOOT STICKER TRANSCAB	\$	na	100.00	305M
1 BOOT STICKER TEL NO	\$	na	100.00	305M
1SET PARKING AID	\$	na	700.00	X
1SET REAR BUMPER CLIP	\$	na	85.00	X
1 REAR BUMPER RETAINER CLIP	\$	na	75.00	X
<b>TOTAL</b>	<b>\$</b>		<b>1,120.00</b>	

**TOTAL PARTS \$ 6,095.20**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	2501
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	4801
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	na	170.00	X
<b>TOTAL</b>	<b>\$</b>		<b>5,100.00</b>	

**Over All Total \$ 11,195.20**

**(PART BY PART) Repair Days**

20 Days  
2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: