

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date 1 Nov 2020

DATE: 13.05.2022

LKK-

MODEL: Hyundai Ioniq

INSURANCE: CHINA TAIPING (P/P)

VEHICLE NO.: SHD4953H

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper <i>X N N ?</i>	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH ?	2	\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding <i>- ee</i>	1		\$ 451.25
	Rear Bumper Lower Centre Moulding <i>?</i>	1		\$ 155.00
	Rear Bumper Cover Clips <i>- ec</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Tow Cover <i>X N N</i>	1		\$ 98.80
	Rear Bumper Reflector LH / RH <i>X N N</i>	2	\$ 41.15	\$ 82.90
	Rear Foglamp <i>?</i>	1		\$ 201.50
SUB TOTAL				\$ 2,141.85
LESS 20% DISCOUNTED TOTAL				\$ 428.37
DISCOUNTED TOTAL				\$ 1,713.48
	Reverse Sensors <i>X N N</i>	1		\$ 180.00
	Rear No. Plate With Trim Cover <i>- OPA</i>	1		\$ 55.00
NETT TOTAL				\$ 235.00
SPARE PARTS TOTAL				\$ 1,948.48
Labour Charge				
	Panel Beating		\$	400.00
	Spray Painting Charge		\$	300.00
	Remove/Refix Reverse Sensor		\$	120.00
TOTAL LABOUR				\$ 820.00
ESTIMATE TOTAL				\$ 2,768.48

350
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
P/P
before part photos
& After part photos
Gino Qiang
13/5/22
4pm

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged parts for a survey
- Part of the repair work to be done on a "no-discount" basis
- Not to be done on a "no-discount" basis
- Not to be done on a "no-discount" basis

Approved and
Signed by the Company