

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4468H

14.05.2022

MAKE REG: 29.12.2016

MODEL HYU- I40

Type

CHIANG/ CHINA

Qty	Parts Description/ Labour	Unit Price	Amount	
1	REAR BUMPER COVER / <i>RC</i>		\$553.00	✓
1	REAR BUMPER LOWER COVER / <i>RC</i>		\$228.00	✓
10	REAR BUMPER CLIPS / <i>RC</i>	\$2.20	\$22.00	✓
1	REAR BUMPER REFLECTOR LH X		\$32.00	
1	REAR BUMPER BRACKET LH X		\$35.60	
1	REAR BUMPER REINFORCEMENT X		\$428.40	
	SUB TOTAL		\$1,299.00	
	20.00% DISCOUNTED TOTAL		\$259.80	
			\$1,039.20	
1	REAR BUMPER MAT / <i>RC</i>		\$50.00	✓
1	REAR BUMPER ADVERTISEMENT / <i>RC</i>		\$50.00	✓
1	REAR REVERSE SENSOR X <i>NN</i>		\$135.70	
			\$222.13	
	Labour Charge			
	Panel Beating		\$450.00	280
	Spray Painting Charge		\$300.00	250
	Remove/refix reverse sensor		\$60.00	40
	Check Lighting & Wiring		\$40.00	X <i>NN</i>
	TOTAL LABOUR		\$850.00	
	ESTIMATE TOTAL		\$2,111.33	
This is an initial estimate based on a visual inspection of the <u>above</u> vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

28 Days -

4/5

After repair photos.

Gano Qiaap

17/5/22 3:30pm

1050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for inspection
- Parts prices to be agreed on a fair basis
- Third party claims to be settled on a fair basis
- No illegal practices to be allowed
- Supplier to be approved and is subject to final approval by insurance company

Acknowledged by Repairer

Signature:

Date: