

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004817/AQY3N2**Date:** 15/06/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00097242200

**Claimant Vehicle  
No :** SKR5385G**Insured Vehicle  
No :** SMA3317H

Date of Loss: 17/05/2022

Nature of Claim: TP

Claim  
No: SNM22D203389C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKR5385G**

Make &amp; Model: HONDA CIVIC, 1.5 (A)

Engine No: R16A13002577

Reg. Date: 27/02/2008 (Man. Year: 2008)

Chassis No: JHMFD46208S200935

Colour: Bronze

Odometer: 186330 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 5,788.52          | 3,215.60          | 2,572.92          | 44.45         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,930.00          | 1,510.00          | 1,420.00          | 48.46         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>8,718.52</b>   | <b>4,725.60</b>   | <b>3,992.92</b>   | <b>45.80</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>3,700.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>8,718.52</b>   | <b>3,700.00</b>   | <b>5,018.52</b>   | <b>57.56</b>  |

**INSPECTION**

Date of Assignment: 23/05/2022

Date Inspected: 24/05/2022

Inspected At: 10 KAKI BUKIT ROAD 2  
#03-25 FIRST EAST CENTRE  
SINGAPORE 417868

Estimated Period of Repair: 5.0 days

REPAIRER: MCS GARAGE

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 15 Jun 2022)         |
| <b>Parts:</b>        | 143  | HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKR5385G)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                    | Repair        | 683.60 FL  | *- FL      |
| 2   | 1   |          | *REAR BUMPER MUDFLAP            | Cut           | 89.90 FL   | *89.90 FL  |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINERS-L/R | Not Necessary | 97.80 FL   | *- FL      |
| 4   | 1   |          | *REAR DOOR-LH                   | Dented        | 941.60 FL  | *941.60 FL |
| 5   | 1   |          | *REAR DOOR PROTECTOR            | Cut           | 186.40 FL  | *186.40 FL |
| 6   | 1   |          | *REAR DOOR GLASS OUTER MOULDING | Not Necessary | 121.30 FL  | *- FL      |
| 7   | 1   |          | *REAR DOOR GLASS RUN CHANNEL    | Not Necessary | 189.60 FL  | *- FL      |
| 8   | 1   |          | *REAR DOOR W/STRIP              | Not Necessary | 126.60 FL  | *- FL      |
| 9   | 1   |          | *REAR DOOR INSULATION           | Not Necessary | 120.30 FL  | *- FL      |
| 10  | 1   |          | *REAR FENDER-LH                 | Repair        | 931.60 FL  | *- FL      |
| 11  | 1   |          | *REAR SHOCK ABSORBER-LH         | Bent          | 380.90 FL  | *380.90 FL |
| 12  | 1   |          | *REAR TOP ARM                   | Bent          | 291.60 FL  | *291.60 FL |
| 13  | 1   |          | *REAR TRAILING ARM              | Bent          | 580.90 FL  | *580.90 FL |
| 14  | 1   |          | *REAR KNUCKLE ARM               | Damaged       | 481.60 FL  | *481.60 FL |
| 15  | 1   |          | *REAR WHEEL HUB BEARING         | Damaged       | 491.60 FL  | *491.60 FL |
| 16  | 1   |          | *REAR WINDSCREEN MOULDING       | Not Necessary | 89.10 FL   | *- FL      |
| 17  | 1   |          | *REAR SPORT WHEEL-LH            | Cut           | 550.00 FS  | *400.00 FS |
| 18  | 1   |          | *REAR TYRE-LH                   | Not Necessary | 350.00 FS  | *- FS      |
| 19  | 1   |          | *SET REAR DOOR BLACK TAPE       | Necessary     | 120.00 FS  | *60.00 FS  |
| 20  | 1   |          | *SET REAR BUMPER CLIP           | Not Necessary | 45.00 FS   | *- FS      |
| 21  | 1   |          | *SET REAR WINDSCREEN SEALANT    | Not Necessary | 80.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>6,949.40</b> | <b>3,904.50</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,160.88        | 688.90          |
| <b>Total Parts (\$)</b>                                  | <b>5,788.52</b> | <b>3,215.60</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO REMOVE,REFIX REAR UNDERCARRIAGE                    | New      | 300.00          | 220.00          |
| 2                               | TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR  | New      | 120.00          | 60.00           |
| 3                               | TO REMOVE,REFIX REAR WINDSCREEN                       | New      | 180.00          | 0.00            |
| 4                               | TO CHECK WHEEL ALIGNMENT                              | New      | 120.00          | 80.00           |
| 5                               | TO RESPRAY UNDERCOATING                               | New      | 80.00           | 50.00           |
| 6                               | TO RESPRAY PAINTING AND ETC                           | New      | 1,080.00        | 600.00          |
| 7                               | PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS | New      | 1,050.00        | 500.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>2,930.00</b> | <b>1,510.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >