MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322 TP China Xiao Chan.

Vehicle number: <u>SKR5385G</u>

Vehicle Made & Model: HONDA CIVIC

	List Items		Amount \$
1	Rear bumper Revi		683.60 X
1	Rear bumper mudflap &		89.90
2	Rear bumper side retainers - L/R @ 48.90	Men	97.80 -
1	Rear door-LH Devted		941.60
1	Rear door protector (ut		186.40
1	Rear door glass outer moulding }		121.30
1	Rear door glass run channel		189.60ҳ
1	Rear door w/strip 7 Mg		126.60 ⊁
1	Rear door insulation \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		120.30 \
1	Rear fender-LH Rys		931.60 ^X .
1	Rear shock absorber - LH Best	2	380.90
1		2755.60	291.60
1	Rear trailing arm	2755.60	580.90
1	Rear knuckle arm 75d		481.60
1	Rear wheel hub bearing 2~2		491.60
1	Rear windscreen moulding whe rec		89.10 X
	The state of the s	Sub-total	5,804.40
		Less 20%	1,160.88
		Total List	4,643.52
	Special Nett Items		
1	Rear sport wheel - LH &	11/2	550.00 400
1	Rear tyre-LH Hem	460	350.00 ≿
-	Rear door black tape ************************************		120.00 60.
	Rear bumper clip 7 2		45.00 X
1 set	Rear windscreen sealant Ku		80.00 X.
1 300	11001	Total Special Nett	1,145.00

Vehicle number: SKR5385G Vehicle Made & Model: HONDA CIVIC

Labour Cirar 200	La	bo	ur	cha	rges
------------------	----	----	----	-----	------

To remove, refix rear undercarriage	300.00 220.
To remove, refix rear interior trims to assist repair	1 20.00 60 180.00 ×
To remove, refix rear windscreen	
To check wheel alignment	130.00 80.
To respray undercoating /5/0	80.00 50
To respray painting and etc	1,080.00 600
Panel beating, cut, weld remove & replacing above parts	1,050.00 500
Total Labour	2,930.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

8,718.52

total: 4725-60 HS: 3.7K-OSDays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: