

**VAC AUTO CENTRE PTE LTD** UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Regn No : SBN8226R

Chassis Number: JF1SJGK85JG112711

Vehicle Make/Model: Subaru Forester 2.0 XT

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
<u>Cost Price Items:</u>				
1	Front fender LH	1	\$ 240.00	\$ 240.00
2	Front fender inner shield LH	1	\$ 105.00	\$ 105.00
3	Front fender bracket LH	2	\$ 20.00	\$ 40.00
4	Front shock absorber LH	1	\$ 280.00	\$ 280.00
5	Front shock absorber LH top mounting	1	\$ 90.00	\$ 90.00
6	Front knuckle arm LH	1	\$ 268.00	\$ 268.00
7	Front knuckle bearing LH	1	\$ 175.00	\$ 175.00
8	Front lower arm	1	\$ 320.00	\$ 320.00
9	Anti-roll bar endlink LH	1	\$ 55.00	\$ 55.00
10	Front bumper	1	\$ 360.00	\$ 360.00
11	Front bumper retainer LH/RH	2	\$ 25.00	\$ 50.00
12	Front bumper lower garnish	1	\$ 245.00	\$ 245.00
13	Front bumper vertical garnish LH	1	\$ 148.00	\$ 148.00
14	Front headlamp assembly LH	1	\$ 2,800.00	\$ 2,800.00
15	Front headlamp lower brackets LH	1	\$ 40.00	\$ 40.00
16	Front headlamp mouldings LH	1	\$ 120.00	\$ 120.00
			Sub-total	\$ 5,336.00
Plus			15%	\$ 800.40
Cost Plus Items			Sub-total	\$ 6,136.40
<u>Special Nett Items:</u>				
1	Front bumper clips	10	\$ 3.00	\$ 30.00
2	Front tyre LH	1	\$ 280.00	\$ 280.00
3	Front wheel rim LH	1	\$ 450.00	\$ 450.00
S/Nett Items			Total	\$ 760.00
<u>Labour Charge Items:</u>				
1	To check electrical wiring systems			\$ 80.00
2	To conduct computerized 4-wheel alignment			\$ 120.00
3	To remove front LH shock absorber, knuckle arm, bearing, endlink, etc			\$ 160.00
4	To diagnose, erase fault memory code after repair			\$ 80.00
5	To respray painting & etc			\$ 850.00
6	Panel beating, cut, weld, remove and replacing above parts			\$ 800.00
Labour Charge			Total	\$ 2,090.00
Overall Estimate Parts & Labour			Grand total	\$ 8,986.40

**Hidden, inaccessible damage parts shall be submitted through supplementary*