



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22004818/Uqy3s2	
			Date: 30/05/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SBN 8226R
	Policy No.	Z/22/VP05/031006	Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/025757	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	23/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER 2.0 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JF1SJGK85JG112711	Colour	GREY
	Odometer	063120 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	23/05/2022
	Survey held at	VAC AUTO CENTRE PL NO.1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$90,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	