

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3389D

Make : HYUNDAI

Model : IONIQ(G3)

Date: 17/05/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT BUMPER COVER <i>Repair x</i>			\$ 481.10	
10	FRT BUMPER CLIPS <i>x</i>			\$ 22.00	
1	FRT BUMPER SIDE BRACKET LH <i>x</i> <i>5na</i>			\$ 28.00	
1	HEADLAMP LH <i>x</i> <i>NN</i>			\$ 2,110.30	
1	FRT FENDER LH <i>/ Bmc</i>			\$ 588.80	✓
1	EMBLEM - BLUE DRIVE LH <i>/ MC</i>			\$ 26.60	✓
1	FRT WHEEL HUB CAP LH <i>/ GA</i>			\$ 346.40	✓
SUB TOTAL				\$ 3,603.20	
LESS 20%				\$ 720.64	
DISCOUNTED TOTAL				\$ 2,882.56	769.44
				\$ -	nett
Labour Charge					
PANEL BEATING				\$ 800.00	350
SPRAY PAINTING CHARGE				\$ 600.00	500
TUFF KOTE				\$ 60.00	40
CHECK ALL LIGHTING				\$ 60.00	X NN
TOTAL LABOUR				\$ 1,520.00	
ESTIMATE TOTAL				\$ 4,402.56	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3 Days

P/P

refue paint photos

Gus Eng

17/5/22

3:30 pm

1659.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car after resurvey
- Parts prices on "best price" basis
- Third party survey on "best price" basis
- No illegal modification
- Supplemental charges are covered and is subject to final approval by Insurance Company

Acknowledged by Repairer
Signature:
Date: