

CITYCAR PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC 813K

DATE 19.05.2022

MAKE REG.16.01.2022

MODEL : HYU IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH X NN			\$35.00
1	FRONT BUMPER / re			\$481.10
1	FRONT SUPPORT PANEL X NN			\$949.30
1	FRONT BUMPER CENTRE MOULDING X Paint Cut			\$368.50
1	FRONT BUMPER GRILLE RH / mis			\$186.50
1	FRONT DAY LIGHT RH / Cut			\$642.50
1	RADIATOR GRILLE X NN			\$1,409.10
1	FRONT FENDER SHIELD RH X Paint TN			\$164.70
1	HEAD LAMP RH / Cut			\$2,110.30
	SUB TOTAL			\$6,347.00
	20.00%			\$1,269.40
	DISCOUNTED TOTAL			\$5,077.60
	FRONT NUMBER PLATE W/HOLDER X NN			\$50.00
				\$50.00
	Labour Charge			
	Panel Beating			\$760.00
	Spray Paint			\$600.00
	Reset Wheel alignment			\$60.00
	Check lighting			\$60.00
	TOTAL LABOUR			\$1,480.00
	ESTIMATE TOTAL			\$6,607.60
D/P 2 Days. before paint photos. Am. Chiang 19/5/22 1pm				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

350
500
X NN
30

LKK Auto Centre

the Repairer's liability

- To resurvey and re-estimate the repair quantum
- To display damaged parts for inspection
- Parts price list
- Third party surveyor's report
- No illegal modification

Acknowledged by Repairer

Signature:

Date: