

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

13/6/22 have h.a
2/5 @ 12.000 informed Alan

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Ashu

Not Available
Link
23/5/22
1/58 12,000 /
8 days.

VEHICLE No: SKE 8211Z

1PC	TAILGATE	11		\$2,665.00	X
1PC	TAILGATE REAR LOGO	11		\$105.00	X
1PC	TAILGATE 'A3' EMBLEM	11		\$82.00	X
1PC	TAILGATE 'TFSI' EMBLEM	11		\$85.00	X
1PC	TAILGATE INNER LOCK	11		\$421.00	X
2PCS	TAILGATE REFLECTORS @\$650.00	11		\$1,399.00	X
1PC	TAILGATE WEATHERSTRIP	SC		\$322.00	X
1PC	REAR BUMPER	Re / Torn	1866.21	\$2,245.00	X
1PC	REAR BUMPER LOWER	SC	385.50	\$981.00	/
2PCS	REAR BUMPER REFLECTORS @\$115.00	11		\$230.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$90.00	11		\$180.00	X
4PCS	REAR BUMPER PDC SENSORS @\$180.00	clunk		\$720.00	2pc 360
1PC	REAR BUMPER BEAM	SC	565.00	\$715.00	/
1PC	REAR BUMPER SPONGE	NP		\$185.00	X
1PC	REAR BUMPER TOP RETAINER	CN	205.40	\$285.00	/
1PC	REAR END PANEL	R		\$1,122.00	X
1PC	REAR END PANEL TOP GARNISH	11		\$305.00	X
2PCS	TAILLAMPS @\$980.00	11		\$1,960.00	X
1PC	BONNET	R		\$3,320.00	X
1PC	BONNET LOCK	11		\$290.00	X
1PC	FRONT BUMPER	Re / Torn	1920.35	\$2,146.00	/
1PC	FRONT BUMPER REINFORCEMENT	SC	605.00	\$855.00	/
1PC	FRONT BUMPER SPONGE	Torn	168.50	\$252.00	/
1PC	FRONT BUMPER INNER RETAINER	Torn	172.30	\$310.00	/
1PC	FRONT GRILLE ASSY	CN	765.00	\$885.00	/
1PC	FRONT SUPPORT PANEL	CN	680.00	\$780.00	/
2PCS	FRONT AIR GUIDES @\$75.00	SC		\$150.00	X
1PC	CONDENSER	11		\$882.00	X
1PC	RADIATOR	11		\$950.00	X
2PCS	HEADLAMPS @\$2810.00	CN	2600x2 = 5200	\$5,620.00	/
2PCS	FRONT FENDERS @\$755.00	R		\$1,510.00	X
				\$31,957.00	

S.NETT

1SET	FRONT BUMPER CLIPS	SC		\$50.00	✓
1PC	FRONT LICENCE PLATE	SC		\$50.00	40
1SET	REAR BUMPER CLIPS	SC		\$50.00	✓
1PC	REAR END PANEL SEALANT	11		\$50.00	X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$180.00	50
TO TRANSFER TAILGATE MECHANISM	11 \$100.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	80
TO SPRAT RUST PROOFING	11 \$120.00	X
TO REFILL AIR CON GAS	\$120.00	100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,200.00	1100
TO PUTTY & SPRAY PAINTING	\$2,200.00	1250
TOTAL	\$37,507.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

12893.26
52
12248.59
140
2660
15048