

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 92313123

Fax: 6452 0614

Vehicle:	SLF3042K
Model:	HONDA VEZEL 1.5X CVT ABS
Chassis:	RU11110217

NO	DESCRIPTION	QTY	COST	MARK UP 10% PRICE	SURVEYORS MARKING
1	FRONT BUMPER ✓ DIS	1	\$ 210.00	\$ 231.00	
2	BUMPER RETAINER ✓ DIS	1	\$ 11.00	\$ 12.10	
3	BUMPER REINFORCEMENT ✓ BT	1	\$ 230.00	\$ 253.00	
4	BUMPER LOWER LIP GARNISH ✓ MIS	1	\$ 145.00	\$ 159.50	
5	FRONT SUPPORT PANEL ?	1	\$ 400.00	\$ 440.00	
6	TOP SUPPORT PANEL GARNISH ✓ DE	1	\$ 45.00	\$ 49.50	
7	FRONT GRILL BASE ?	1	\$ 210.00	\$ 231.00	
8	FRONT GRILL PANEL ?	1	\$ 170.00	\$ 187.00	
9	FRONT GRILL CHROME TRIM ?	1	\$ 23.00	\$ 25.30	
10	FRONT LOWER GRILL ✓ CUT	1	\$ 60.00	\$ 66.00	
11	FRONT GRILL CENTRE DUCT BRACKET ?	1	\$ 25.00	\$ 27.50	
12	FRONT LOWER AIR DUCT COVER ?	1	\$ 48.00	\$ 52.80	
13	FRONT AUR DUCT HOSE ?	1	\$ 35.00	\$ 38.50	
14	BONNET ✓ BUC	1	\$ 470.00	\$ 517.00	
15	BONNET HINGE LHS ✓ BT	1	\$ 32.00	\$ 35.20	
16	BONNET HINGE RHS ✓ BT	1	\$ 32.00	\$ 35.20	
17	BONNET INSULATOR ?	1	\$ 85.00	\$ 93.50	
18	BONNET STAY ?	1	\$ 30.00	\$ 33.00	
19	BONNET LOCK ✓ BT	1	\$ 75.00	\$ 82.50	
20	FRONT BONNET SEAL ✓ TWI	1	\$ 20.00	\$ 22.00	
21	FENDER RHS ✓ DIS	1	\$ 220.00	\$ 242.00	
22	FENDER INNER SHIELD COVER RHS ?	1	\$ 85.00	\$ 93.50	
23	FENDER ARCH PANEL RHS ✓ MIS	1	\$ 60.00	\$ 66.00	
24	RADIATOR ASSY ?	1	\$ 870.00	\$ 957.00	
25	RADIATOR BRACKET ?	1	\$ 15.00	\$ 16.50	
26	CONDENSOR ASSY ✓ CUT	1	\$ 400.00	\$ 440.00	
27	WIPER TANK ✓ DE	1	\$ 70.00	\$ 77.00	
28	ENGINE MANIFOLD ?	1	\$ 380.00	\$ 418.00	
29	FAN COVER BIG ?	1	\$ 40.00	\$ 44.00	
30	FAN COVER SMALL ?	1	\$ 45.00	\$ 49.50	
31	FAN BLADE SMALL ?	1	\$ 50.00	\$ 55.00	
32	FAN BLADE BIG ?	1	\$ 50.00	\$ 55.00	
33	FRONT AIRBAG SENSOR ✓ ACT	1	\$ 155.00	\$ 170.50	
34	HEADLAMP ASSY RHS ✓ CRA	1	\$ 1,100.00	\$ 1,210.00	
35	HEADLAMP BRACKET ?	1	\$ 24.00	\$ 26.40	
36	FOG LAMP ASSY ✓ MIS	1	\$ 160.00	\$ 176.00	
37	FOG LAMP GARNISH COVER ✓ MIS	1	\$ 20.00	\$ 22.00	
38	DASH BOARD ASSY ✓ CRA	1	\$ 720.00	\$ 792.00	
39	DRIVER AIRBAG ✓ ACT	1	\$ 930.00	\$ 1,023.00	
40	PASSENGER AIRBAG ✓ ACT	1	\$ 1,100.00	\$ 1,210.00	
41	AIRBAG ECU ?	1	\$ 790.00	\$ 869.00	
42	FRONT SEAT BELT ASSY ✓ ACT	1	\$ 445.00	\$ 489.50	
43	SEAT BLETSIDE LOWER GARNISH ?	1	\$ 60.00	\$ 66.00	
44	FRONT DOOR RHS X Repair	1	\$ 560.00	\$ 616.00	

45	AIRCON SUCTION HOSE ?	1	\$	135.00	\$	148.50	
46	AIRCON DISCHARGE HOSE ?	1	\$	105.00	\$	115.50	
47		1			\$	-	
48		1			\$	-	
	TOTAL:				\$	12,039.50	

	SPECIAL NETT	PRICE	SURVEYOR MARKING
1	BUMPER CLIPS ✓ NEC	\$ 50.00	
2	FENDER INNER SHIELD CLIPS ✓ NEC	\$ 50.00	
3			
3			
	SPECIAL NETT	\$ 100.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEAT- ACCIDENT AREA	\$ 1,200.00	600
2	SPRAY PAINT- FRONT BONNET INNER/OUTER, FRONT BUMPER, FRONT FENDER LHS/RHS, FRONT DOOR RHS, BONNET HINGE X 2, SUPPORT PANEL	\$ 1,800.00	1000
3	RUST PROOFING	\$ 60.00	✓
4	REMOVE AND REFIT DOOR FRHS COMPONENTS	\$ 150.00	X NN
5	REMOVE AND REFIT DOOR FRHS REGULATOR MOTOR	\$ 150.00	X NN
6	REMOVE AND REFIT DOOR GLASS FRHS TO TRANSFER	\$ 150.00	X NN
7	REMOVE AND REFIT DASHBOARD	\$ 300.00	200
8	REMOVE AND REFIT AIRBAG PASSENGER AND DRIVER	\$ 450.00	100
9	DIAGNOSTICS AND CLEAR FAULT CODE	\$ 450.00	X NN
10	REMOVE AND REFIT SEAT BELT X 2	\$ 250.00	100
11	CHECK WIRING AND CHECK ALIGNMENT	\$ 60.00	30
12	TOP UP AIRCON GAS	\$ 50.00	✓
13	TOP UP COOLANT	\$ 50.00	✓
	TOTAL:	\$ 5,120.00	

5 Days

Lumpsum repair

After repair photos

Excess: TBA

Not Authorised

Guo Qiang - LKK

82880282

GuoQiang@lkkauto.com

24/05/2022

PARTS	\$ 12,039.50	
LABOUR	\$ 5,120.00	
SPECIAL NETT	\$ 100.00	
TOTAL	\$ 17,259.50	
GST 7%	\$ 1,208.17	
FINAL TOTAL	\$ 18,467.67	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: