

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-May-22

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6903 U

2 pcs	Front o/s & n/s head lamp @1028
1 pc	Bonnet grille
1 pc	Front bumper
1 pc	Front bumper emblem
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00
1 pc	Front bumper n/s upper bracket
1 pc	Front bumper n/s support bracket
1 pc	Front bumper o/s protector
1 pc	Front bumper o/s fog light cover
1 pc	Front door LH
1 pc	Front n/s wheel cover
1 pc	Front n/s fender
1 pc	Front n/s fender inner shield

repair

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

### S/NETT

1 set	Front bumper clips
1 pc	Front n/s fender sticker
1 set	Front n/s fender inner shield clips

Acknowledged by Repairer

Signature:

Date:

Sundry

To focus and adjust front n/s & o/s head lamps

Towing fee

To check front wheel alignment

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

To putty and spray painting on front bumper, front n/s fender, bonnet, front o/s fender

To apply rustproofing on the repaired and replaced panels.

\$	2,056.00	nn
\$	385.00	X nn
\$	531.00	dl
\$	44.00	nd
\$	32.00	dl
\$	16.00	X nn
\$	16.00	X nn
\$	51.00	cut
\$	66.00	cut
\$	-	X nn
\$	116.00	X nn
\$	384.00	bt
\$	120.00	fn
\$	3,817.00	2256
\$	337.90	2030.40
\$	3,479.10	

\$	48.00	Zone
\$	30.00	u
\$	28.00	u

\$	50.00	X nn
\$	60.00	Zone
\$	50.00	
\$	80.00	X nn

\$	800.00	500
----	--------	-----

\$	900.00	800
\$	80.00	30

\$ 5,605.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

3528.40  
\* 415 \$2800 103 days  
Tampin 22495747  
wp, 23/5/22 2530 pm  
LBS Resurvey after repair  
Tampin 22495747  
23/5/22