




TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

Vehicle number	SLC7093C
Make / Model	TOYOTA ALTIS
Chassis number	MR053REH104540171
Accident date	5/5/22
Reference	2205-34

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR DOOR RH	1323 1455.30 1455.30 / DT
1	REAR DOOR WEATHERSTRIP RH	189.30 189.30 / net
1	REAR DOOR INNER TRIM BOARD RH	672 869.00 869.00 / cat
1	REAR DOOR REGULATOR RH	295.24 295.24 / X Svc
1	REAR DOOR REGULATOR MOTOR RH	762.7 822.03 822.03 / sam
1	REAR DOOR LOCK RH	482.30 482.30 / Svc
1	REAR DOOR TAPE RH	98.90 98.90 / nic
1	REAR DOOR CHROME MOUDLING RH	160.82 160.82 / nic
1	REAR FENDER RH	972.10 972.10 / X Svc
1	REAR FENDER INNER SHIELD RH	219.30 219.30 / X Svc
1	REAR SHOCK ABSORBER RH	254.32 254.32 / X Svc
1	REAR WHEEL HUB W BEARING RH	570 1117.27 1117.27 / DIS
1	REAR BUMPER	648.45 648.45 / X Svc
1	REAR BUMPER RETAINER RH	98.90 98.90 / nic
		7683.23
	Less 25%	1920.81
		5762.42
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR RIM RH	500.00 500.00 / Svc 300
1 SET	REAR BUMPER CLIP	30.00 30.00 / nic
1 SET	REAR FENDER INNER SHIELD CLIP	30.00 30.00 / nic
	Subtotal	560.00
	Balance C/F	6322.42
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	100.00 30
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	150.00 60
3	REMOVE & REPLACE REAR UNDERCARRIAGE	150.00 150.00 / X NVN
4	REMOVE & REFIT REVERSE SENSOR	120.00 30
5	REMOVE DOOR TRIMS & MECHANISM	150.00 70
6	PANEL BEATING ON AFFECTED AREAS	1000.00 600
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600
8	APPLY ANTI RUST ON AFFECTED AREAS	100.00 30
	Subtotal	2770.00
	Grand total	9092.42

Thuan
82235769 LIS
26/5/22 scays w/p
1700

3750 / F: ~~82235769~~ = 3750
Rp. 5