

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 710W

Vehicle: IN / OUT

Date:

Person Contacted:

L7A817624

Date / Time

Action / Instruction

Tailgate n/c

Veh No:

GBE61440

Yr Regn:

23/01/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Nissan NV350

c.c

2488

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

112206

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN/MC2E2620005644

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

35

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/05/22

D.O.I.

27/05/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS, \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

15/2/23 2/5 1500 vehicle hasn't send in for repair

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE6144D/2205067

23th May 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 15th May 2022
Location : PIE Exit to Jln Eunos
Third Party Claim Vehicle No : SMD 7843 M
Repair Cost For Vehicle No : GBE 6144 D Nissan NV350

not Authorised
27/5/22
3 days.
1/581500

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover	R 1	1,916.00	\$ 1,916.00 X
2	Rear boot cover emblem (logo)	11 1	95.90	\$ 95.90 X
3	Rear boot cover emblem (NV 350)	11 1	110.00	\$ 110.00 ✓
4	Rear windscreen glass	11 1	1,000.00	\$ 1,000.00 X
5	Rear end panel	R 1	286.10	\$ 286.10 X
6	Rear bumper fascia	11 1	573.10	\$ 573.10 ✓
7	Rear bumper clips	11 1set	50.00	\$ 50.00 ✓
8	Rear bumper sensor(s/nett)	11 1set	380.00	\$ 380.00 2005/w
9	Rear boot cover sticker (70km/h) (s/nett)	11 1	28.00	\$ 28.00 105/w
10	Rear windscreen sealant (s/nett)	11 1	60.00	\$ 60.00 X
11	Rear windscreen sealer (s/nett)	11 1	80.00	\$ 80.00 X
				\$ 4,579.10

nett item

(102)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE6144D/2205067

23th May 2022

Balance b/f	\$ 4,579.10
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 980.00 450
Remove & refix rear bumper sensor	\$ 80.00 50
Remove & refix rear windscreen glass	^^ \$ 120.00 X
Tuff-kote on damage parts	^^ \$ 80.00 X
Spray painting on damage parts	\$ 1,080.00 500
Check all lighting after repairs	\$ 30.00 20
Labour Charge	\$ 2,370.00
Total Amount	\$ 6,949.10

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-733-1
102
658-79
210
1020