



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date:

23/5/2022

Vehicle:

SNB3543D

Make / Model:

TOYOTA PRIUS

INSURANCE

No.	Description	Unit	Unit Price	Amount	
1	TAILGATE <i>buc /</i>	1	\$ 1,359.00	\$ 1,359.00	929
2	TAILGATE WEATHERSTRIP <i>nc /</i>	1	\$ 212.00	\$ 212.00	198
3	TAILGATE OUTER GARNISH <i>de /</i>	1	\$ 521.00	\$ 521.00	280
4	TAILGATE EMBLEM PRIUS t <i>nc /</i>	1	\$ 89.40	\$ 89.40	52.30
5	TAILGATE EMBLEM HYBRID <i>nc /</i>	1	\$ 82.30	\$ 82.30	50
6	TAILGATE DETECTOR <i>X nn</i>	1	\$ 321.00	\$ 321.00	X
7	TAILGATE LOCK <i>cut /</i>	1	\$ 312.00	\$ 312.00	/
8	TAILAMP LH <i>ca /</i>	1	\$ 612.00	\$ 612.00	596
9	TAILAMP LOWER BRACKET LH <i>ca /</i>	1	\$ 48.00	\$ 48.00	/
10	REAR BUMPER <i>de /</i>	1	\$ 658.00	\$ 658.00	549
11	REAR BUMPER SIDE RETAINER <i>X nn</i>	2	\$ 112.00	\$ 224.00	X
12	REAR BUMPER REINFORCEMENT <i>h /</i>	1	\$ 398.20	\$ 398.20	350.50
13	REAR BUMPER BRACKET <i>bt / lpc RH</i>	1	\$ 114.00	\$ 228.00	115.30
14	* REAR BUMPER LIP <i>de /</i>	1	\$ 728.90	\$ 728.90	550
15	REAR BUMPER UNDER COVER LH <i>X nn</i>	1	\$ 321.00	\$ 321.00	X
16	REAR BUMPER UNDER COVER RH <i>X nn</i>	1	\$ 251.00	\$ 251.00	X
17	REAR FENDER INNER TRIM <i>X nn</i>	2	\$ 612.00	\$ 1,218.00	X
18	REAR END PANEL <i>bt</i>	1	\$ 598.00	\$ 598.00	517.89
19	REAR END PANEL TOP GARNISH <i>cut /</i>	1	\$ 312.00	\$ 312.00	225.10
20	REAR FLOOR PANEL <i>X nn</i>	1	\$ 1,151.00	\$ 1,151.00	X
21	REAR FLOOR PANEL TOP BOARD <i>X nn</i>	1	\$ 398.00	\$ 398.00	X
22	REAR FLOOR PANEL TOP SIDE SPONGE <i>de /</i>	1	\$ 522.00	\$ 522.00	396.70
	<i>NA X REAR bumper chr cover - de - price</i>	NPA	25%	\$ 10,564.80	
421	<i>TAILGATE INNER TRIM - ca / price</i>		Less 20%	\$ 2,112.96	
			Total	\$ 8,451.84	
	S/Nett items:				
1	REAR BUMPER CLIPS <i>nc /</i>	1	\$ 80.00	\$ 80.00	30
2	REAR TAILGATE INNER TRIM BOARD CLIPS <i>nc /</i>	1	\$ 80.00	\$ 80.00	30
3	REAR FENDER INNER TRIM CLIPS SET <i>X</i>	1	\$ 50.00	\$ 50.00	XM
4	REAR REVERSE SENSOR <i>nc /</i>	1	\$ 250.00	\$ 250.00	200
5	REAR END PANEL TOP GARNISH CLIPS <i>nc /</i>	1	\$ 80.00	\$ 80.00	30
6	REAR END PANEL SEALANT <i>nc /</i>	1	\$ 60.00	\$ 60.00	40
				\$ 600.00	330
	Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING <i>nc /</i>	1	\$ 150.00	\$ 150.00	30
2	TO REMOVE AND RENEW REVERSE SENSOR <i>nc /</i>	1	\$ 150.00	\$ 150.00	60
3	TO REMOVE AND REFIT REAR GLASS <i>nc /</i>	1	\$ 150.00	\$ 150.00	120
4	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY <i>nc /</i>	1	\$ 200.00	\$ 200.00	60
5	REMOVE AND RENEW TAILGATE MECHANISM <i>nc /</i>	1	\$ 80.00	\$ 80.00	40
6	REMOVE AND RENEW REAR EXHAUST SILENCER <i>X</i>	1	\$ 150.00	\$ 150.00	X nn

7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	X 11
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	60
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00	700
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00	700
				\$ 4,030.00	1770
			Parts Replacement Amount	\$ 9,051.84	
			Total Amount for Labour	\$ 4,030.00	
			Total Amount	\$ 13,081.84	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Hp 90010068

5 days

L/S

23/05/22 @ 17W

Reg after
repair

4193.09

330.00

1770.00

6293.09

202

5034.47

L/S \$5,000