

03/1/2022 wef

ASS. REC. BY:


REF: CS/ASM22004844/DVC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SH 8345K
 Policy No. _____
 Claims No. S2M03ZFT
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBQ339K Yr Regn: July, 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda FS150F C.C. 149

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 40640 T/Radio: Insured / Std / NI / NA

Eng/No: KC27E2234510

C/No: PM PMKKC2760KB221425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80 R17

R: 120/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

R/Bal. 2 mm

L/Bal. mm

D.O.A. 21/04/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

W/S Portion y Rear Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AXA SH 8345K

MV 8.5K

VIA 2.1K

NL 6.4K

30/07/2022 Jinchuan 4S 2,300/- with 4 days. of rep (red 3806, 62%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 2/8/22-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format : TP

Lump Sum /+B+ (\$ 2300)

TOTAL



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng

105 Woodlands St. 13 #03-180

Singapore 730105.

Honda FS150F

Estimate Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Lamp (Brake Lamp Assy) <i>broken</i>		240.00	✓
2 Pcs. Rear Signal Lamp <i>broken</i>	@ 58.00	116.00	✓
2 Pcs. Rear Reflector <i>HN</i>	@ 28.00	56.00	X
1 Pc. Rear Lamp Garnish <i>broken</i>		99.00	✓
1 Pc. Rear Lamp Top Cover <i>HN</i>		178.00	X
2 Pcs. Rear Lamp Bottom Cover <i>HN</i>	@ 198.00	396.00	X
1 Pc. Rear Fender <i>broken</i>		148.00	✓
1 Pc. Rear Fender Dust Garnish <i>broken</i>		180.00	✓
2 Pcs. Rear RS150R Emblem <i>HN</i>	@ 45.00	90.00	✓
1 Pc. Rear Toolbox <i>changed</i>		399.00	✓ 180/- SH
1 Pc. Rear Toolbox Holder <i>cut</i>		185.00	✓
2 Pcs. Rear Foot Rest <i>o/s HN n/s cut</i>	@ 60.00	120.00	✓
2 Pcs. Centre Foot Rest <i>o/s HN n/s cut</i>	@ 63.00	126.00	✓
1 Pc. Foot Gear Lever <i>st</i>		98.00	✓
1 Pc. Exhaust Pipe Assy <i>HN</i>		480.00	X
1 Pc. Exhaust Garnish <i>cut</i>		120.00	✓
1 Pc. Tyre <i>HN</i>		280.00	X
1 Pc. Sport Rim <i>HN</i>		410.00	X
1 Pc. Rear Wheel Shaft <i>HN</i>		120.00	X
<i>Rev</i> 1 Set Front Side Fairing <i>cut</i>		495.00	✓
<i>Rev</i> 1 Set Front Side Fairing Sticker <i>HN</i>		160.00	✓
<i>Rev</i> 1 Set Front Side Fairing Honda Sticker <i>HN</i>		90.00	X
1 Pc. Clutch Lever <i>cut</i>		110.00	✓
1 Pc. Side Mirror LH <i>broken</i>		98.00	✓
1 Pc. Rear Number Plate <i>st/cut</i>		30.00	✓ 15/- SH

Total (Panels / Parts): 4,824.00 (SGD)

SH 195.00 //

Less 2262.00

10% 2035.80 //



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit lamp and check wire.	80.00	20/-
To remove & refit renew rear tyre & rim.	60.00	15/-
To repair & renew all accident affected area.	480.00	120/- 250/-
To respray painting on all accident affected damaged Parts.	400.00	100/- 150/-

Total (Labor Charges): 1,020.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	4,824.00	2665.80
LABOR CHARGES	1,020.00	235.80
		<u>2901.60</u>
		L/S 2,130.00/-
Grand Total:	5,844.00 (SGD)	

We shall be glad if you can forward the payment at your early convenience.

**For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E**

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

24/05/2022 @ 1000hrs
 Noted
 2/June
 4 days
 Check part prices.
 Page 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng
105 Woodlands St. 13 #03-180
Singapore 730105.

Honda FS150F

Supplementary Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Brake Centre Reflector <i>broken</i>	28.00✓
1 Pc. Rear Signal Holder <i>broken</i>	90.00✓
1 Pc. Rear Lamp Holder <i>broken</i>	85.00✓
1 Pc. Rear Lamp Holder Rubber <i>WCC</i>	59.00✓

Grand Total: 262.00 (SGD)

262.00
10% *235.80*
=

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

2 yr
2Kk Auto
[Signature]



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng

105 Woodlands St. 13 #03-180

Singapore 730105.

Honda FS150F

Estimate Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Lamp (Brake Lamp Assy) <i>broken</i>		240.00	✓
2 Pcs. Rear Signal Lamp <i>broken</i>	@ 58.00	116.00	✓
2 Pcs. Rear Reflector <i>MM</i>	@ 28.00	56.00	X
1 Pc. Rear Lamp Garnish <i>broken</i>		99.00	✓
1 Pc. Rear Lamp Top Cover <i>MM</i>		178.00	X
2 Pcs. Rear Lamp Bottom Cover <i>MM</i>	@ 198.00	396.00	X
1 Pc. Rear Fender <i>broken</i>		148.00	✓
1 Pc. Rear Fender Dust Garnish <i>broken</i>		180.00	✓
2 Pcs. Rear RS150R Emblem <i>MM</i>	@ 45.00	90.00	✓
1 Pc. Rear Toolbox <i>damaged</i>		399.00	✓
1 Pc. Rear Toolbox Holder <i>cut</i>		185.00	✓
1 Pc. Rear Foot Rest <i>o/s MM H/S cut</i>	@ 60.00	120.00	✓
1 Pc. Centre Foot Rest <i>o/s MM H/S cut</i>	@ 63.00	126.00	✓
1 Pc. Foot Gear Lever. <i>cut</i>		98.00	✓
1 Pc. Exhaust Pipe Assy <i>MM</i>		480.00	X
1 Pc. Exhaust Garnish <i>cut</i>		120.00	✓
1 Pc. Tyre <i>MM</i>		280.00	X
1 Pc. Sport Rim <i>MM</i>		410.00	X
1 Pc. Rear Wheel Shaft <i>MM</i>		120.00	X
<i>Rev</i> 1 Set Front Side Fairing <i>MM cut</i>		495.00	✓
<i>Rev</i> 1 Set Front Side Fairing Sticker <i>MM MM</i>		160.00	✓
<i>Rev</i> 1 Set Front Side Fairing Honda Sticker <i>MM MM</i>		90.00	✓
1 Pc. Clutch Lever <i>cut</i>		110.00	✓
1 Pc. Side Mirror LH <i>broken</i>		98.00	✓
1 Pc. Rear Number Plate <i>cut</i>		30.00	✓
Total (Panels / Parts)		4,824.00 (SGD)	




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit lamp and check wire.	80.00 20/-
To remove & refit renew rear tyre & rim.	60.00 15/-
To repair & renew all accident affected area.	480.00 180/-
To respray painting on all accident affected damaged Parts.	400.00 100/-

Total (Labor Charges): 1,020.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	4,824.00
LABOR CHARGES	1,020.00
Grand Total:	<u>5,844.00 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

24/05/2022. @ 1000hrs

N/A Andrew

2/5/2022

4 days

2kk And

Check part prices.

Page 2 of 2