



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng

105 Woodlands St. 13 #03-180

Singapore 730105.

Honda FS150F

Estimate Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Lamp (Brake Lamp Assy) <i>broken</i>		240.00	✓
2 Pcs. Rear Signal Lamp <i>broken</i>	@ 58.00	116.00	✓
2 Pcs. Rear Reflector <i>HN</i>	@ 28.00	56.00	X
1 Pc. Rear Lamp Garnish <i>broken</i>		99.00	✓
1 Pc. Rear Lamp Top Cover <i>HN</i>		178.00	X
2 Pcs. Rear Lamp Bottom Cover <i>HN</i>	@ 198.00	396.00	X
1 Pc. Rear Fender <i>broken</i>		148.00	✓
1 Pc. Rear Fender Dust Garnish <i>broken</i>		180.00	✓
2 Pcs. Rear RS150R Emblem <i>HN</i>	@ 45.00	90.00	✓
1 Pc. Rear Toolbox <i>changed</i>		399.00	✓ 180/- SH
1 Pc. Rear Toolbox Holder <i>cut</i>		185.00	✓
2 Pcs. Rear Foot Rest <i>o/s HN n/s cut</i>	@ 60.00	120.00	✓
2 Pcs. Centre Foot Rest <i>o/s HN n/s cut</i>	@ 63.00	126.00	✓
1 Pc. Foot Gear Lever <i>st</i>		98.00	✓
1 Pc. Exhaust Pipe Assy <i>HN</i>		480.00	X
1 Pc. Exhaust Garnish <i>cut</i>		120.00	✓
1 Pc. Tyre <i>HN</i>		280.00	X
1 Pc. Sport Rim <i>HN</i>		410.00	X
1 Pc. Rear Wheel Shaft <i>HN</i>		120.00	X
<i>Rev</i> 1 Set Front Side Fairing <i>HN cut</i>		495.00	✓
<i>Rev</i> 1 Set Front Side Fairing Sticker <i>HN HN</i>		160.00	✓
<i>Rev</i> 1 Set Front Side Fairing Honda Sticker <i>HN HN</i>		90.00	X
1 Pc. Clutch Lever <i>cut</i>		110.00	✓
1 Pc. Side Mirror LH <i>broken</i>		98.00	✓
1 Pc. Rear Number Plate <i>st/cut</i>		30.00	✓ 15/- SH

Total (Panels / Parts): 4,824.00 (SGD)

SH 195.00 //

List 2262.00

10% 2035.80 //



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit lamp and check wire.	80.00	20/-
To remove & refit renew rear tyre & rim.	60.00	15/-
To repair & renew all accident affected area.	480.00	120/- 250/-
To respray painting on all accident affected damaged Parts.	400.00	100/- 150/-

Total (Labor Charges): 1,020.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	4,824.00	2665.80
LABOR CHARGES	1,020.00	235.80
		2901.60
		4/5 2,300/-
Grand Total:	5,844.00 (SGD)	

We shall be glad if you can forward the payment at your early convenience.

**For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E**

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

24/05/2022 @ 1000hrs
N/A Andrew
2/June
4 days
2 & k And
Check part prices.

Page 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng
105 Woodlands St. 13 #03-180
Singapore 730105.

Honda FS150F

Supplementary Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Brake Centre Reflector <i>broken</i>	28.00✓
1 Pc. Rear Signal Holder <i>broken</i>	90.00✓
1 Pc. Rear Lamp Holder <i>broken</i>	85.00✓
1 Pc. Rear Lamp Holder Rubber <i>WCC</i>	59.00✓

Grand Total: 262.00 (SGD)

262.00
10% *235.80*
=

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

2 yr
2Kk Auto
[Signature]



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng

105 Woodlands St. 13 #03-180

Singapore 730105.

Honda FS150F

Estimate Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Lamp (Brake Lamp Assy) <i>broken</i>		240.00	✓
2 Pcs. Rear Signal Lamp <i>broken</i>	@ 58.00	116.00	✓
2 Pcs. Rear Reflector <i>MM</i>	@ 28.00	56.00	X
1 Pc. Rear Lamp Garnish <i>broken</i>		99.00	✓
1 Pc. Rear Lamp Top Cover <i>MM</i>		178.00	X
2 Pcs. Rear Lamp Bottom Cover <i>MM</i>	@ 198.00	396.00	X
1 Pc. Rear Fender <i>broken</i>		148.00	✓
1 Pc. Rear Fender Dust Garnish <i>broken</i>		180.00	✓
2 Pcs. Rear RS150R Emblem <i>MM</i>	@ 45.00	90.00	✓
1 Pc. Rear Toolbox <i>damaged</i>		399.00	✓
1 Pc. Rear Toolbox Holder <i>cut</i>		185.00	✓
1 Pc. Rear Foot Rest <i>o/s MM H/S cut</i>	@ 60.00	120.00	✓
1 Pc. Centre Foot Rest <i>o/s MM H/S cut</i>	@ 63.00	126.00	✓
1 Pc. Foot Gear Lever. <i>cut</i>		98.00	✓
1 Pc. Exhaust Pipe Assy <i>MM</i>		480.00	X
1 Pc. Exhaust Garnish <i>cut</i>		120.00	✓
1 Pc. Tyre <i>MM</i>		280.00	X
1 Pc. Sport Rim <i>MM</i>		410.00	X
1 Pc. Rear Wheel Shaft <i>MM</i>		120.00	X
<i>Rev</i> 1 Set Front Side Fairing <i>MM cut</i>		495.00	✓
<i>Rev</i> 1 Set Front Side Fairing Sticker <i>MM Hec</i>		160.00	✓
<i>Rev</i> 1 Set Front Side Fairing Honda Sticker <i>MM Hec</i>		90.00	✓
1 Pc. Clutch Lever <i>cut</i>		110.00	✓
1 Pc. Side Mirror LH <i>broken</i>		98.00	✓
1 Pc. Rear Number Plate <i>cut</i>		30.00	✓
Total (Panels / Parts):		4,824.00 (SGD)	




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit lamp and check wire.	80.00 20/-
To remove & refit renew rear tyre & rim.	60.00 15/-
To repair & renew all accident affected area.	480.00 180/-
To respray painting on all accident affected damaged Parts.	400.00 100/-

Total (Labor Charges): 1,020.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	4,824.00
LABOR CHARGES	1,020.00

Grand Total: 5,844.00 (SGD)

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

24/05/2022. @ 1000hrs

N/A Andrew

2/3mm

4 days

2kk And

Check part prices.

Page 2 of 2