



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 180522

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.05.2022

Yeoh Se Meng
105 Woodlands St. 13 #03-180
Singapore 730105.

Honda FS150F

Supplementary Repair Cost for Motor Cycle Reg. No: FBQ 339 K

1 Pc. Rear Brake Centre Reflector <i>broken</i>	28.00✓
1 Pc. Rear Signal Holder <i>broken</i>	90.00✓
1 Pc. Rear Lamp Holder <i>broken</i>	85.00✓
1 Pc. Rear Lamp Holder Rubber <i>new</i>	59.00✓

Grand Total: 262.00 (SGD)

262.00
10% *235.80*
=

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

2 yr
2Kk Auto
[Signature]