

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SKA6969E

ACCIDENT DATE : 13-05-2022 19:00

THIRD PARTY REF. : SDZ1005X

INVOICE NO : TEST

DATE : 04-08-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE SKA6969E LANDROVER DISCOVERY

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BONNET	2612.00
1	FRONT SUPPORT PANEL	850.00
1	FRONT SUPPORT GARNISH	580.00
1	FRONT GRILLE	850.00
2	FRONT HEADLAMP@\$4279.40	8558.80
1	FRONT FENDER WHEEL ARCH GARNISH RH	485.00
10	FRONT FENDER SHIELD CLIP @\$4.00	40.00
1	FRONT BUMPER	2450.00
2	FRONT BUMPER SIDE RETAINER@\$95.00	190.00
1	FRONT BUMPER REINFORCEMENT	780.00
10	FRONT BUMPER CLIP @\$4.00	40.00
1	INTERCOOLER	1850.00
1	AIR CON CONDENSER	1580.00
1	RADIATOR	1650.00
1	PIPE (A) damaged	85.00
1	HOSE (A) damaged	180.00
		<hr/>
		22,780.80
ADD 10 %		<hr/>
		2,278.08
TOTAL ( A )		<hr/>
		25,058.88

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	30.00
		<hr/>
TOTAL ( C )		<hr/>
		30.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
---	------------------------	-------