



# V-TECH AUTO SERVICE

No.1 Soon Lee St #06-04/05/06/07 Pioneer Centre Singapore 627605

Tel: 62646211, 62646222 Fax: 62646233 Email: vtech.autoservice@gmail.com

Reg. 52949633W, GST Reg No. M90364098A

Website: <http://vtechauto.com.sg>

**24 HRS TOWING SERVICES**

Vehicle No. YP 2418 K

## Parts and Labour Assessment

### Description of part

#### PARTS (LIST ITEMS)

	Qty	Cost
1 FRONT PANEL	1	1,148.10
2 FRONT PANEL 300 STICKER	1	45.00
3 FRONT PANEL HINO STICKER	1	50.00
4 FRONT INNER PANEL	1	887.15
5 HEAD LAMP L/R	2	1,220.00
6 FRONT CENTRE GRILLE ASSY	1	542.20
7 FRONT CENTRE GRILLE ASSY LOGO	1	56.00
8 AIRCON COOLING PIPE	1	340.00
9 AIRCON DISCHARGE PIPE	1	550.00
10 AIRCON SUCTION PIPE	1	410.00
11 AIRCON DRYER UNIT	1	118.00
12 AIRCON BLOWER UNIT	1	893.00
13 AIRCON EVAPORATOR COIL	1	871.20
14 FRONT BUMPER ASSY	1	981.80
15 FRONT BUMPER BRACKET L/R	2	240.20
16 FRONT BUMPER CENTRE INNER BEAM	1	230.00
17 FRONT BUMPER FOG LAMP L/R	2	420.00

Percentage discount 0%

	\$	9,002.65
	\$	-
<b>Sub-total</b>	<b>\$</b>	<b>9,002.65</b>

### SPECIAL NETT ITEMS

1	FRONT PANEL 'LENG AIK' STICKER	1	240.00
2	FRONT GRILLE CLIPS - SET	1	30.00
3	FRONT BUMPER NUMBER PLATE	1	25.00
Sub-total			<u>\$ 295.00</u>

### LABOUR

1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	120.00
2	To remove, change dashboard fascia and transfer where necessary.	350.00
3	To remove, replaced aircon piping, check evaporator unit, aircon blower motor and etc to vaccum system and top up gas.	200.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00
6	To apply anti-rust chemical on repaired and replaced panel.	120.00
Labour Total		<u>\$ 3,190.00</u>
Parts & Labour Total		<u>\$ 12,487.65</u>

Best Regards,