

Plate Number YP2418K	Case Number MCV2022D0002603	Brand Toyota	Model Details Hiace	Body Type MPV	Insurance company India International Insurance
Technician -	SA LKK_assignments	Parts Manager -			

No data

Remarks 1 remarks

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Note: Re confirm on the spare parts price before finalize

Pre Review By : Insurlogic

Amount : \$5513.10

Check items: \$4069.35

Repair Duration: 5 working days
