

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 02 Jun 2022

Preliminary Advice

Vehicle No	: YP2418K	Accident Date	: 19/05/2022
Make	: HINO XZU710R	Policy No.	: D20MCV0004095_01
Assignment Date	: 23/05/2022	Excess	: S\$750.00
Date of Inspection	: 24/05/2022	Est. Duration of Repair	: 5
Inspection At	: V-TECH AUTO SERVICE (HQ) NO.1 SOON LEE STREET, #06-04 PIONEER CENTER SINGAPORE 627605		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,487.65
Revised Amount	:S\$	5,513.10
Check Items (Estimated)	:S\$	4,069.35
Total	:S\$	9,582.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	11,732.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,268.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair. According to repairer they are unable to locate 2nd hand parts.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .