

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0400/2022/JT
DATE : 18-May-22
WIP : 24204

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

27-Sep-22

OWNER'S NAME : MR HONG JYE SENG
ADDRESS : BLK 46 CHOA CHU KANG ST 63
#04-22
SINGAPORE 689106
TELEPHONE : HP +65 94517909
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 18000137641-02
VEHICLE NO : **SMG 8787 U**
MODEL CODE : AUDI A3 SB 1.4 TFSI
MODEL YEAR : 11/10/2018
ENGINE NO : CZE 824009
CHASSIS NO : WAUZZZ8V6JA145831
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-May-22
PLACE OF ACCIDENT : TECK WHYE AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 8787 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$	2,042.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8787 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,146.00	\$	1,716.80
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 332.00		
6	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 318.00		
7	RADIATOR GRILLE	1	\$ 1,578.00		
8	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00		
9	AIR COND STICKER	1	\$ 9.00		
10	CAUTION STICKER	1	\$ 16.00		
11	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 210.00		
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00		
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 136.00		
14	FRONT BUMPER REINFORCEMENT	1	\$ 846.00		
15	FRONT FENDER - RH	1	\$ 954.00		
16	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
17	FRONT FENDER BRACKET - RH	1	\$ 56.00		
18	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 68.00		
19	FRONT FENDER BRACE - RH	1	\$ 107.00		
20	FRONT FENDER POP RIVET	8	\$ 31.00		
SUB TOTAL SPARE PARTS		:	\$ 7,720.00	\$	1,716.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8787 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 1,716.80
21	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 60.00	
23	HEADLIGHT - RH	1	\$ 5,879.00	\$ 4,364.00
24	LIFT CYLINDER - RH	1	\$ 156.00	
25	LIFT CYLINDER HOSE	1	\$ 78.00	
26	RADIATOR AIR GUIDE - RH	1	\$ 28.00	
27	RADIATOR SEAL - RH OUTER	1	\$ 9.00	
28	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	
29	FRONT NO PLATE	S/N	\$ 100.00	
30	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 14,577.00	\$ 6,080.80
TOTAL LABOUR CHARGES			\$ 5,002.00	\$ 2,042.00
GRAND TOTAL			\$ 19,579.00	\$ 8,122.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-07/09/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT