

Case Details

Case Reference Number :

TAX/05/22/2024

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5799R

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18238-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 09/05/2022 08:05 AM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price	List Price(\$)	Dis(%)			Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	521.00 ✓	521.00	25.00	390.75	Replace	1	390.75	Replace ✓	del ✓
Standard	Main			SUPPORT, FR BUMPER RH	1	80.10	80.10	25.00	60.07	Replace	0	0	Not Give ✓	Xun
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30 ✓	82.30	25.00	61.72	Replace	1	61.72	Replace ✓	del ✓
Standard	Main			GRILLE, RADIATOR	1	178.60	178.60	25.00	133.95	Replace	0	0	Not Give ✓	Xun
Standard	Main			GRILLE SUB-ASSY	1	422.50	422.50	25.00	316.88	Replace	0	0	Not Give ✓	Xun
Standard	Main			GRILLE, SUB - ASSY , 2	1	160.50	160.50	25.00	120.38	Replace	0	0	Not Give ✓	Xun
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50 ✓	45.00	25.00	33.75	Replace	10	33.75	Replace ✓	del ✓
Standard	Main			MOULDING, FRONT BUMPER SIDE, LH	1	95.60 ✓	95.60	25.00	71.70	Replace	1	71.70	Replace ✓	out ✓
Standard	Main			ABSORBER, FR BUMPER LOWER	1	132.70	132.70	25.00	99.52	Replace	0	0	Not Give ✓	Xun
Standard	Main			ABSORBER, FR BUMPER	1	80.20	80.20	25.00	60.15	Replace	0	0	Not Give ✓	Xun
Standard	Main			RETAINER, FR BUMPER, LH & RH	2	8.80	17.60	25.00	13.20	Replace	0	0	Not Give ✓	Xun
Standard	Main			PAD, FRONT BUMPER (NO.1)	1	40.70	40.70	25.00	30.53	Replace	0	0	Not Give ✓	Xun
Standard	Main			PAD, FRONT BUMPER (NO.2)	1	36.00	36.00	25.00	27.00	Replace	0	0	Not Give ✓	Xun
Standard	Main			REINFORCEMENT FRONT LOWER	1	246.10	246.10	25.00	184.58	Replace	0	0	Not Give ✓	Xun

Total Spare Part Cost 9,307.24

Surveyor Total 1,489.95

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,307.24

Final Sur Total 1,489.95

22, 10:44

SOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REINFORCEMENT FRONT UPPER	1	716.60	716.60	25.00	537.45	Replace	0	0	Not Give	Xun
Standard	Main			UNIT, HEADLAMP, LH	1	2,637.60	2,637.60	10.00	2,373.84	Replace	0	0	Not Give	Xun
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	3,772.50	3,772.50	10.00	3,395.25	Replace	0	0	Not Give	Xun
Standard	Main			LAMP ASSY, FOG, LH	1	237.10	237.10	10.00	213.39	Replace	0	0	Not Give	Xun
Standard	Main			COVER, ENGINE UNDER CENTER	1	98.00	98.00	25.00	73.50	Replace	0	0	Not Give	Xun
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	80.10	80.10	25.00	60.07	Replace	0	0	Not Give	Xun
Standard	Main			FENDER SUB-ASSY, FR, LH	1	977.80	977.80	25.00	733.35	Replace	1	733.35	Replace	ht ✓
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	ney ✓
Standard	Main			LINER, FR FENDER, LH	1	210.30	210.30	25.00	157.73	Replace	1	157.73	Replace	de ✓
Standard	Main			RETAINER, FR WHEEL RH	1	3.20	3.20	25.00	2.40	Replace	0	0	Not Give	Xun
Standard	Main			PROTECTOR, FR FENDER LH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	Xun
Standard	Main			PAD, FR WHEEL LH	1	59.60	59.60	25.00	44.70	Replace	0	0	Not Give	Xun
Total Spare Part Cost									9,307.24	Surveyor Total 1,489.95				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									9,307.24	Final Sur Total 1,489.95				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	845.00	300	
Total:			845.00	300.00 ✓	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			936.00	400.00 ✓	

1986.60
25% 1489.95

022, 10:44
for Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			380.00	30.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	9,307.24	1,489.95
Total Labour Cost	845.00	300.00
Total Spray Painting	936.00	400.00
Other	380.00	30.00
Overall Total	11,468.24	2,219.95
Lump Sum Repair Option		☐
Lump Sum Total	0.00	2,219.95
Surveyor Approved Amount		2,219.95
No of Repair Days*	5	3
Remarks		PART BY PART REPAIR / BEFORE PAINT PHOTO /
Surveyor Name		Taufikh
Signature		

Survey Date 11/05/2022

Save Clear

1489.95
300
400
30
2219.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Taufikh 97415749
WP 4/5/22 @ 425
P/P Resing before part 03 days
03 days
taufikh@lkkhard.com