

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2022
User ID PohSuan
Section A - Accident Details

Registration Number	SHB5799R
Case Reference Number	TAX/05/22/2024
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHUA LAK KHOON
Type of Accident	Side Swipe
Accident Date and Time	9/5/2022 4:05 PM
Accident Reported Date and Time	10/5/2022 10:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114874
Special Instruction to ARC, if any	BP / LEFT FRONT PORTION
Prepared Date and Time	10/5/2022 1:18 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$9,307.24	\$1,489.96
Total Other Cost	\$380.00	\$30.00
TOTAL COST	\$11,468.24	\$2,219.96 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / NTUC
ARC / Surveyor Sign Off Date	10/05/2022 1:33 PM	11/05/2022 4:43 PM
Signature		
Remarks		PART BY PART REPAIR / BEFORE PAINT PHOTO /.

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2022

User ID : PohSuan

		81220-12240	LAMP ASSY, FOG, LH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given	X
		51447-47030	COVER, ENGINE UNDER CENTER	0.00	\$98.00	0.00	\$0.00	Replace	Not Given	X
		51444-12080	COVER, ENGINE UNDER SIDE LH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$977.80	25.00	\$733.35	Replace	Replace	✓
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace	✓
		53876-47060	LINER, FR FENDER, LH	1.00	\$210.30	25.00	\$157.73	Replace	Replace	✓
		53857-12010	RETAINER, FR WHEEL RH	0.00	\$3.20	0.00	\$0.00	Replace	Not Given	X
		53828-47070	PROTECTOR, FR FENDER LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X
		53852-47041	PAD, FR WHEEL LH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given	X
Total					\$11,030.90		\$1,489.95			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,489.96
 + 300.00
 + 430.00

 2,219.96