

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0426/2022/JT
DATE : 26-May-22
WIP : 25408

Xiao Tony
\$ 6866.96
03 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 27/5/22
YOUR INSURED VEH NO : SKG 7722 L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS MERRY GUNAWAN
ADDRESS : 11 NATHAN ROAD
#23-03
SINGAPORE 248732
TELEPHONE : HP +65 96688927
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00698903/02
VEHICLE NO : SDM 8858 Z
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 27/9/2017
ENGINE NO : DAX 012912
CHASSIS NO : WAUZZZF3H2048510
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-May-22
PLACE OF ACCIDENT : 109 KILINEY ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8858 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X.
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER AND BOTH HEADLIGHTS, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	600
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 5,000.00	1000 Bumper 600 Wheel Arc 200x2=400
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,672.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8858 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Regis</i>	1	\$ 3,131.00	X	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 338.00	X	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2	\$ 84.00	X	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 252.00	X	
5	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 161.00	X	
6	FRONT BUMPER SPOILER <i>new</i>	1	\$ 850.00	X	
7	FRONT BUMPER UNDERRUN BAR	1	\$ 580.00	X	
8	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 246.00	X	
9	RADIATOR GRILLE <i>crushed</i>	1	\$ 3,910.00	X	
10	QUATTRO EMBLEM <i>new</i>	1	\$ 111.00	X	
11	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 271.00	X	
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 1,302.00	X	
13	FRONT BUMPER END CAP - LH / RH <i>new</i>	2	\$ 206.00	X	
14	FRONT BUMPER LOCKING CLIP <i>new</i>	4	\$ 18.00	X	
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 198.00	X	
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,043.00	X	
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 86.00	X	
18	HORN - LH / RH <i>new</i>	2	\$ 416.00	X	
19	FRONT PARKING AID SENSOR - INNER	2	TBC	X	
20	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	X	
SUB TOTAL SPARE PARTS			\$ 13,213.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8858 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - OUTER	2	TBC	X
22	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00	✓
23	HEADLIGHT - LH / RH	2	\$ 17,416.00	X
24	LIFT CYLINDER - LH / RH	2	\$ 306.00	X
25	LIFT CYLINDER HOSE	1	\$ 145.00	X
26	FRONT FENDER - LH / RH	2	\$ 2,924.00	X
27	FRONT FENDER BRACE - LH / RH	2	\$ 500.00	X
28	FRONT FENDER BRACEKT - LH / RH	2	\$ 40.00	X
29	S-LINE EMBLEM	2	\$ 266.00	X
30	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 606.00	X
31	FRONT WHEEL SPOILER - LH / RH	2	\$ 353.00	X
32	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,418.00	✓
33	FRONT BUMPER TOP COVER	1	\$ 144.00	X
34	CAUTION STICKER	1	\$ 16.00	X
35	AIR COND STICKER	1	\$ 22.00	X
36	FRONT NO PLATE	S/N	\$ 60.00	✓
37	SUNDRIES		\$ 350.00	✓
TOTAL SPARE PARTS			\$ 38,043.00	
TOTAL LABOUR CHARGES			\$ 9,672.00	
GRAND TOTAL			\$ 47,715.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

38.86

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian
: 27/05/22

:
: No Authorised, 03 Days
: H.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0426/2022/JT
DATE : 26-May-22
WIP : 25408

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 27/5/22

YOUR INSURED VEH NO : SKG 7722 L

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 9 Sep 22

OWNER'S NAME : MS MERRY GUNAWAN
ADDRESS : 11 NATHAN ROAD
#23-03
SINGAPORE 248732
TELEPHONE : HP +65 96688927
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00698903/02
VEHICLE NO : **SDM 8858 Z**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 27/09/2017
ENGINE NO : DAX 012912
CHASSIS NO : WAUZZZFY3H2048510
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-May-22
PLACE OF ACCIDENT : 109 KILINEY ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8858 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER AND BOTH HEADLIGHTS, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,200.00	\$	600.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS.	\$	5,000.00	\$	1,000.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,672.00	\$	2,272.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8858 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,131.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 338.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 252.00	
5	FRONT BUMPER GRILLE - CENTER	1	\$ 161.00	\$ 128.40
6	FRONT BUMPER SPOILER	1	\$ 850.00	
7	FRONT BUMPER UNDERRUN BAR	1	\$ 580.00	
8	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 246.00	
9	RADIATOR GRILLE	1	\$ 3,910.00	\$ 3,128.00
10	QUATTRO EMBLEM	1	\$ 111.00	
11	RADIATOR GRILLE STRIKER PLATE	1	\$ 271.00	
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,302.00	
13	FRONT BUMPER END CAP - LH / RH	2	\$ 206.00	
14	FRONT BUMPER LOCKING CLIP	4	\$ 18.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 198.00	
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,043.00	
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	
18	HORN - LH / RH	2	\$ 416.00	
19	FRONT PARKING AID SENSOR - INNER	2	TBC	
20	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	
SUB TOTAL SPARE PARTS		:	\$ 13,213.00	\$ 3,256.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8858 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 3,256.40
21		2	TBC	
22	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00	\$ 105.20
23	HEADLIGHT - LH / RH	2	\$ 17,416.00	
24	LIFT CYLINDER - LH / RH	2	\$ 306.00	
25	LIFT CYLINDER HOSE	1	\$ 145.00	
26	FRONT FENDER - LH / RH	2	\$ 2,924.00	
27	FRONT FENDER BRACE - LH / RH	2	\$ 500.00	
28	FRONT FENDER BRACEKT - LH / RH	2	\$ 40.00	
29	S-LINE EMBLEM	2	\$ 266.00	
30	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 606.00	
31	FRONT WHEEL SPOILER - LH / RH	2	\$ 353.00	
32	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,418.00	\$ 1,134.40
33	FRONT BUMPER TOP COVER	1	\$ 144.00	
34	CAUTION STICKER	1	\$ 16.00	
35	AIR COND STICKER	1	\$ 22.00	
36	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
37	SUNDRIES		\$ 350.00	\$ 38.96
TOTAL SPARE PARTS			\$ 38,043.00	\$ 4,594.96
TOTAL LABOUR CHARGES			\$ 9,672.00	\$ 2,272.00
GRAND TOTAL			\$ 47,715.00	\$ 6,866.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-21/08/22