



# 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

DA/FC(SMB281R)

DOA: 10/05/2022@0640

MS FIRST CAPITAL INSURANCE PTE LTD

23/05/2022

ATTN: THE MOTOR CLAIMS DEPT

## THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKX 642 R - TOYOTA WISH 1.8 CVT

CHASSIS NO: JTDGG20W90J003130 (2015)

|       |                                                                                                                                                     |             |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| 1 pc  | Rear windscreen moulding                                                                                                                            | \$ 115.00   |
| 1 pc  | Rear boot                                                                                                                                           | \$ 1,400.00 |
| 1 pc  | Rear boot logo                                                                                                                                      | \$ 45.00    |
| 1 pc  | Rear bumper                                                                                                                                         | \$ 595.00   |
| 1 pc  | Rear bumper retainer LHS                                                                                                                            | \$ 95.00    |
| 1 pc  | Rear bumper retainer RHS                                                                                                                            | \$ 95.00    |
| 1 pc  | Rear end panel                                                                                                                                      | \$ 467.00   |
| 1 pc  | Rear end panel top garnish                                                                                                                          | \$ 245.00   |
|       |                                                                                                                                                     | <hr/>       |
|       |                                                                                                                                                     | \$ 3,057.00 |
|       | LESS 25%                                                                                                                                            | \$ 764.25   |
|       |                                                                                                                                                     | <hr/>       |
|       |                                                                                                                                                     | \$ 2,292.75 |
| 1 pc  | Rear no.plate (S/NETT)                                                                                                                              | \$ 35.00    |
| 1 set | Reverse sensor (S/NETT)                                                                                                                             | \$ 200.00   |
| 1 pc  | Rear windscreen sealant (S/NETT)                                                                                                                    | \$ 35.00    |
|       | Remove and reinstall rear windscreen                                                                                                                | \$ 120.00   |
|       | Check wiring function                                                                                                                               | \$ 40.00    |
|       | Remove and install cushions, seats back rest, inner trim, garnish,<br>roof lining and upholstery to facilitate repair.                              | \$ 180.00   |
|       | Apply rust-proofing                                                                                                                                 | \$ 120.00   |
|       | Remove necessary parts: jacking, panel beating, repair and<br>straighten rear inner panel, spare tyre compartment inclusive<br>replacing the above. | \$ 800.00   |
|       | Putty and respray rear inner panel, rear end panel, rear boot, rear<br>bumper and spare tyre compartment.                                           | \$ 800.00   |
|       |                                                                                                                                                     | <hr/>       |
|       |                                                                                                                                                     | \$ 4,622.75 |
|       | ADD 7% GST                                                                                                                                          | \$ 323.59   |
|       |                                                                                                                                                     | <hr/>       |
|       |                                                                                                                                                     | \$ 4,946.34 |

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....  
