



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004875/Eny3e2	
			Date: 14/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 281R	Veh. Inspected	SKX 642R	
Policy No.	D-19094584MFBP	Coverage (\$)	0.00	
Claim No.	D22001428MFBP	Excess (\$)	0.00	
Assign From	HARMINDER KAUR	Assign Date	24/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDGG20W90J003130	Colour	SILVER	
Odometer	129920 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	4 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/05/2022	Inspection Date	25/05/2022	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	