

創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SMB281R)

DOA: 10/05/2022@0640

MS FIRST CAPITAL INSURANCE PTE LTD

10/06/2022

ATTN: THE MOTOR CLAIMS DEPT


THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKX 642 R - TOYOTA WISH 1.8 CVT
CHASSIS NO: JTDGG20W90J003130 (2015)

Supplementary

1 pc	Rear taillamp LHS	✓ BR	\$	318.99	
	LESS 25%		\$	79.75	
			\$	239.24	✓
	Repair rear fender LHS		\$	80.00	✓
	Putty and respray rear fender LHS		\$	200.00	✓
			\$	519.24	519.24
	ADD 7% GST		\$	36.35	
			\$	555.59	

CHARN'S CUSTOMCRAFT

Parts - 1687.50
S/W - 270.00
Lab - 1610.00
SUPP - 239.24
3806.74
UB - 3800/-



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Stew (LKK)
25/5/22, 11.00
DA/FC(SMB281R)
DOA: 10/05/2022@0640

m h
4 yr
L/S, M, M, G

MS FIRST CAPITAL INSURANCE PTE LTD

23/05/2022

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKX 642 R - TOYOTA WISH 1.8 CVT

CHASSIS NO: JTDGG20W90J003130 (2015)

1 pc	Rear windscreen moulding	✓ n/c	\$	115.00
1 pc	Rear boot	✓ 00	\$	1,400.00
1 pc	Rear boot logo	✓ n/c	\$	45.00
1 pc	Rear bumper	✓ BR	\$	595.00
1 pc	Rear bumper retainer LHS	✓ BR	\$	95.00
1 pc	Rear bumper retainer RHS	✓	\$	95.00
1 pc	Rear end panel	✓	\$	467.00
1 pc	Rear end panel top garnish	✓	\$	245.00

LESS 25%

\$ 3,057.00
\$ 764.25
\$ 2,292.75

1 pc	Rear no.plate (S/NETT)	✓ CUT	\$	35.00
1 set	Reverse sensor (S/NETT)	✓ Panel	\$	200.00
1 pc	Rear windscreen sealant (S/NETT)	✓ n/c	\$	35.00

Remove and reinstall rear windscreen \$ 120.00

Check wiring function \$ 40.00

Remove and install cushions, seats back rest, inner trim, garnish, roof lining and upholstery to facilitate repair. \$ 180.00

Apply rust-proofing \$ 120.00

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, spare tyre compartment inclusive replacing the above. \$ 800.00

Putty and respray rear inner panel, rear end panel, rear boot, rear bumper and spare tyre compartment. \$ 800.00

ADD 7% GST

\$ 4,622.75
\$ 323.59
\$ 4,946.34

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

repair
2250
562.50
1687.50
repair end panel
400 + 100
600