

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	'198R GST Reg. No. 19-	9607198-R	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI22004876/Avy3m4	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 10/10/2022	
			Co	ode: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJB 8849L	Veh. Inspected	SLV 1610A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015395/JM	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	24/05/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PICNIC	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	JTEGH23B400027097	Colour	BLUE	
	Odometer	284021 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/05/2022	Inspection Date	24/05/2022	
	Survey held at	RYDER AUTO PTE LTD	•		
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III / (COOKDAIN	Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: