

(08/11/13)

ASS. REC. BY:

REF:

C9/CT12200 4883/Bgy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 4167KYr Regn: 04/6/2018Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUZUKI EVERY JOINc.c. TURBO AT655Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: DA17V8 21962.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 155 R12R: "BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Windforce

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 25/5/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Finalised LS to 10500, 14 days (Red \$12108.06, 54%)20/05/23 RE-finalised LS \$9450, 14 days. (due to calculation error)
(Red \$13158.06, 58%)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2) _____

Report Format : MER-TPLump Sum / I.B.: (\$) 10500 9450Days Of Repair: 14Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

22/05

12/05/23

500 OER

1000

PROMPT MOTORS PTE.LTD.
BLK 8 KAKI BUKIT AVENUE 4 #02-16
PREMIER @ KAKI BUKIT
SINGAPORE 415875
UEN: 202214492N

Repair Estimate

Vehicle number: GBH4167K
Make & Model: Suzuki Every Join
Chassis number: DA17V821962

Date of survey: _____
Name of surveyor: _____
Contacts: _____

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ 863.00
2	Bonnet RH hinge	1	\$ 55.30
3	Bonnet LH hinge	1	\$ 55.30
4	Bonnet emblem	1	\$ 34.70
5	Bonnet lock	1	\$ 65.10
6	Front bumper	1	\$ 638.00
7	Front bumper clips	1set	\$ 30.00 50.00
8	Front bumper RH side retainer	1	\$ 28.70
9	Front bumper LH side retainer	1	\$ 28.70
10	RH headlamp	1	\$ 374.20
11	LH headlamp	1	\$ 374.20
12	Support panel	1	\$ 550.60
13	Aircon condenser	1	\$ 623.10
14	Radiator assy	1	\$ 732.40
15	Front RH fender	1	\$ 383.40
16	Front RH fender splash shield	1	\$ 74.00
17	Front RH fender splash shield clips	1set	\$ 20.00 30.00
18	Tailgate	1	\$ 986.10
19	Tailgate lock	1	\$ 178.30
20	Tailgate lock catch	1	\$ 35.50
21	Tailgate outer handle	1	\$ 78.40
22	Tailgate weatherstrip	1	\$ 144.90
23	Rear bumper	1	\$ 594.30
24	Rear bumper clips	1set	\$ 30.00 50.00
25	Rear bumper RH retainer	1	\$ 33.40
26	Rear bumper LH retainer	1	\$ 33.40
27	Rear bumper LH lamp	1	\$ 99.40
28	Rear bumper RH lamp	1	\$ 99.40
29	Rear bumper number plate lamp	1	\$ 35.80
30	Rear bumper number plate lamp bracket	1	\$ 28.70
31	End panel	1	\$ 654.90
32	End panel LH air duct	1	\$ 42.10
33	End panel RH air duct	1	\$ 42.10
34	Exhaust silencer	1	\$ 452.90
35	Exhaust silencer gasket	1	\$ 48.00
36	Exhaust silencer rubber mounting	1	\$ 29.80
37	LH rear fender	1	\$ 873.60
38	LH rear fender inner trim	1	\$ 101.00
39	LH rear fender inner trim clips	1set	\$ 20.00 50.00
40	LH rear fender splash shield	1	\$ 67.40
41	LH rear fender splash shield clips	1set	\$ 20.00 30.00

DDV
NDX
NECV
NDX
DDV
NECV
NECV
BRV
BTV
BTV
BTV
NDX
BRV
NECV
DDV
JM
NDX
NDX
TJV
DDV
NECV
NECV
BRV
NDX
DDV
NDX
BRV
BTV
NECV
NNX
NDX
NDX
NECV
DISV
NECV

42	RH rear fender	1	\$ 873.60
43	RH rear fender inner trim	1	\$ 401.00
44	RH rear fender inner trim clips	1set	\$ 20.00 50.00
45	RH rear fender splash shield	1	\$ 67.40
46	RH rear fender splash shield clips	1set	\$ 20.00 30.00
47	Spare tyre carriage	1	\$ 377.20
48	Floor panel	1	\$ 1,372.00
49	Floor panel RH insulator	1	\$ 143.50
50	Floor panel LH insulator	1	\$ 143.50

NDX
NDX
NECV
DISV
NECV
BTX
BTX
NDX

\$ 12,908.30
Parts less 15% \$ 1,936.25
Total \$ 10,972.06

No.	Special Nett Items		Amount S\$
1	Front number plate	1	\$ 40.00 70.00
2	Radiator coolant	1	\$ 30.00 60.00
3	Tailgate art work sticker * provide invoice	1	\$ 1,200.00
4	Tailgate "70km/h" sticker	1	\$ 10.00 28.00
5	Tailgate "Spax" sticker	1	\$ 18.00 28.00
6	Tailgate windscreen glass sealant	1	\$ 20.00 20.00
7	Tailgate windscreen glass inner seal	1	\$ 50.00
8	Rear number plate	1	\$ 40.00 70.00
9	Rear bumper reverse sensor	1set	\$ 200.00 320.00
10	RH rear fender advertisement sticker	1	\$ 1,200.00
11	RH rear fender joint sealant	1	\$ 70.00
12	LH rear fender advertisement sticker	1	\$ 1,200.00
13	LH rear fender joint sealant	1	\$ 70.00

BTX
NECV
NECV
NECV
NNX
NECV
SCV
NNX
NNX
NNX
NNX

Total: \$ 4,436.00

No.	Labour and painting	Amount S\$
	(FRONT PORTION)	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 600.00 1,000.00
2	Spray painting on affected areas and panels	\$ 600.00 1,000.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 50.00
5	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 120.00 280.00
6	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$ 50.00 250.00

NNX

7	Refocus and adjust headlamps assy	\$ 50.00	NNX
(REAR PORTION)			
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1000.00	✓
2	Spray painting on affected areas and panels	\$ 800.00	✓
3	Check wiring and lighting system on affected areas	\$ 80.00	} NNX
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 120.00	✓
6	Remove and replace tailgate inner mechanism to new door	\$ 80.00	✓
7	Remove and replace rear bumper reverse sensor to assist repair	\$ 60.00	✓
8	Remove and replace exhaust silencer and rubber moulding to assist repair	\$ 60.00	✓
9	Remove and replace rear inner trims and boards to assist repair	\$ 280.00	NN
Total:		\$ 7,200.00	

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 10,972.06

Special Nett: \$ 4,436.00

Labour: \$ 7,200.00

Total Amount: \$ 22,608.06

Survey & Resurvey

25/5/2022

1400 hrs

Totum In

Lump sum repair

Repair days 14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____