

Vehicle Damage Assessment Report for [SMT9176H]

Estimate Created: 24/05/2022 06:27 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 22/07/2022 09:02 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Fit
Engine Type			
License Plate Number	SMT9176H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Recommended cost of repair at lump sum \$1200.00 with 4 days for repair	Insurlogic 1 (22/07/2022 09:01)
---	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT DOOR RH		1	831.00	-20.00 %	664.80
FRONT DOOR FRAME TAPE		1	35.80	-20.00 %	28.64

Parts Subtotal 693.44

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE FRONT DOOR RH	RnR	100.00	0.00 %	100.00
TRANSFER DOOR FITTING	RnR	60.00	0.00 %	60.00
ANTI RUST	RnR	30.00	0.00 %	30.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REPAIR REAR DOOR AND REAR FENDER RH	Unknown	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
FRONT DOOR RH, REAR DOOR RH AND REAR FENDER RH	Full spray	550.00	0.00 %	550.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 290.00

Paint Labor Subtotal 550.00

Labor Subtotal 840.00

Summary

Repair Cost	1,533.44
Discount(22 %)	(333.44)
	1,200.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,200.00