

dee OFR

AK

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKX925P
Make & Model: Hyundai Tuscon
Chassis number: KMHJ3813MGU072594

Date of survey: _____
Name of surveyor: _____
Contacts: _____

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate	1	\$ 1,758.90	DD ✓
2	Tailgate windscreen glass rubber moulding	1	\$ 143.60	NECV ✓
3	Tailgate centre emblem	1	\$ 33.20	NECV ✓
4	Tailgate RH lamp	1	\$ 932.70	} BR ✓
5	Tailgate LH lamp	1	\$ 932.70	
6	Tailgate outer garnish	1	\$ 221.00	BR ✓
7	Tailgate outer garnish clips	1set	\$ 60.00	NNX
8	Tailgate "Tucson" emblem	1	\$ 29.10	NECV ✓
9	Tailgate lock	1	\$ 192 ✓ 677.00	JMV ✓
10	Tailgate lock catch	1	\$ 53.00	NDX
11	Tailgate weatherstrip	1	\$ 129.50	NDX
12	Tailgate RH electronic damper	1	\$ 1,009.59	} NDX
13	Tailgate LH electronic damper	1	\$ 1,009.59	
14	Tailgate inner trim board	1	\$ 289.50	BR ✓
15	Tailgate inner trim board clips	1set	\$ 30.00 ✓ 60.00	NECV ✓
16	Tailgate RH number plate lamp	1	\$ 88.40	} NDX
17	Tailgate LH number plate lamp	1	\$ 88.40	
18	Rear bumper (upper)	1	\$ 447.80	BR ✓
19	Rear bumper clips (upper)	1set	\$ 30.00 ✓ 60.00	NECV ✓
20	Rear bumper (lower)	1	\$ 354.60	BR ✓
21	Rear bumper clips (lower)	1set	\$ 30.00 ✓ 60.00	NECV ✓
22	Rear bumper RH reflector	1	\$ 104.90	} BR ✓
23	Rear bumper LH reflector	1	\$ 104.90	
24	Rear bumper RH side reverse sensor	1	\$ 140.50	NDX
25	Rear bumper RH centre reverse sensor	1	\$ 140.50	} SCV
26	Rear bumper LH centre reverse sensor	1	\$ 140.50	
27	Rear bumper LH side reverse sensor	1	\$ 140.50	
28	Rear bumper reverse sensor holders	4	\$ 92.00	NNX
29	Rear bumper reverse sensor wire harness	1	\$ 368.70	} NDX
30	Rear bumper RH blind spot sensor	1	\$ 1,397.40	
31	Rear bumper LH blind spot sensor	1	\$ 1,397.40	BR ✓
32	Rear bumper RH side garnish	1	\$ 22.10	} NDX
33	Rear bumper LH side garnish	1	\$ 22.10	
34	Rear bumper reinforcement	1	\$ 280.60	BR ✓
35	Rear bumper RH side retainer	1	\$ 26.60	} NECV ✓
36	Rear bumper LH side retainer	1	\$ 26.60	
37	RH taillamp assy	1	\$ 903.10	BR ✓

38	RH taillamp side garnish	1	\$	149.70	NNX
39	LH taillamp assy	1	\$	✓ 903.10	BR✓
40	LH taillamp side garnish	1	\$	149.70	NNX
41	End panel	1	\$	✓ 739.40	DD✓
42	End panel inner garnish	1	\$	✓ 78.30	BR✓
43	End panel inner garnish clips	1set	\$	30.00 ✓ 50.00	NEC✓
44	Rear RH fender splash shield	1	\$	78.80	} NDX
45	Rear RH fender splash shield clips	1set	\$	20.00	
46	Rear RH fender inner trim board	1	\$	✓ 355.40	BR✓
47	Rear RH fender inner trim board clips	1set	\$	20.00 ✓ 40.00	NEC✓
48	Rear RH fender arch garnish	1	\$	67.80	} NDX
49	Rear RH fender arch garnish clips	1set	\$	28.00	
50	Rear LH fender splash shield	1	\$	78.80	} NDX
51	Rear LH fender splash shield clips	1set	\$	20.00	
52	Rear LH fender inner trim board	1	\$	✓ 355.40	BR✓
53	Rear LH fender inner trim board clips	1set	\$	20.00 ✓ 40.00	NEC✓
54	Rear LH fender arch garnish	1	\$	67.80	} NDX
55	Rear LH fender arch garnish clips	1set	\$	28.00	
56	Exhaust silencer	1	\$	✓ 852.80	DD✓
57	Exhaust silencer gasket	1	\$	✓ 56.30	NEC✓
58	Exhaust silencer heat shield	1	\$	131.20	NSX
			\$	18,037.48	12,101.40
			Parts less 20%	\$ 3,607.50	-20%
			Total	\$ 14,429.98	9681.12

No.	Special Nett Items		Amount S\$	
1	Tailgate windscreen glass sealant	1	\$ 40.00 ✓ 70.00	NEC ✓
2	Tailgate windscreen glass inner seal	1	\$ 30.00 ✓ 50.00	NEC
3	Tailgate reverse camera	1	\$ 750.00	NDX
4	Rear number plate	1	\$ 50 ✓ 70.00	DDV ✓
5	End panel joint sealant	1	\$ 30.00 ✓ 70.00	NEC ✓
		Total:	\$ 1,010.00	150

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800.00 1,500.00 ✓
2	Spray painting on affected areas and panels	\$ 800.00 1,300.00 ✓
3	Check wiring and lighting system on affected areas	\$ -80.00 } NSX
4	Apply rust coating chemical on affected areas and panels	\$ 120.00 }
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 120.00 220.00 ✓
6	Remove and replace tailgate reverse camera to assist repair	\$ 120.00 NSX

7	Remove and replace tailgate inner mechanism to assist repair	\$ 80.00 180.00 ✓
8	Remove and replace rear bumper reverse sensors to assist repair	\$ 60.00 150.00 ✓
9	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 280.00 NN X
10	Remove and replace exhaust silencer and gasket to assist repair	\$ 60.00 180.00 ✓
Total:		\$ 4,130.00

1920

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 14,429.98
Special Nett: \$ 1,010.00
Labour: \$ 4,130.00

Total Amount: \$ 19,569.98

11,751.12

L/S - 9400.89
= 9400

Survey & Resurvey

25/5/2022

Tellin hms

1425 hrs

Lump sum repair
Repair days 9

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: