



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22004892/Upa3q2 Date: 04/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMJ 8741K	Veh. Inspected	SMV 6516U	
Policy No.	P2271968	Coverage (\$)	0.00	
Claim No.	S2M041YG	Excess (\$)	0.00	
Assign From		Assign Date	24/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ESTIMA AERAS 3.5 (A)	c.c	3456	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	GSR500006694	Colour	GREY	
Odometer	133750 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/45 ZR18	LANVIGATOR	6 mm	
L/H Front Tyre	245/45 ZR18	LANVIGATOR	6 mm	
R/H Rear Tyre	245/45 ZR18	LANVIGATOR	6 mm	
L/H Rear Tyre	245/45 ZR18	LANVIGATOR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/05/2022	Inspection Date	24/05/2022	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	