

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 02 Jun 2022

Preliminary Advice

Insured : YP2038Z

Vehicle No

TP Vehicle : SDA5595P
No

Accident Date : 23/05/2022

Make : TOYOTA CAMRY

Assignment Date : 24/05/2022

Date of : 24/05/2022

Est. Duration of : 2

Inspection

Repair

Inspection At : FASTECH AUTO PTE LTD (HQ)
1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY
SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,610.90
Revised Amount	:S\$	1,750.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,750.58

Lump Sum Repair	:S\$	1,400.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.