

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	730E
Vehicle Details	
Vehicle No.:	SKU5617Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	PE20663981
Chassis No.:	JM6GJ1072G0211221
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$17,368.00
Original Registration Date:	31 Jul 2015
First Registration Date:	31 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$17,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2025
PARF Rebate Amount:	\$11,289.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,509.00
COE Rebate Amount:	\$22,894.00
Total Rebate Amount:	\$34,183.00

The information contained herein is correct as at 17 May 2022

OK

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
11 Pym \$4600/-
Resurvey After Pym
6 day,

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: Third Party

Accident Date : 05.05.2022

Date: 20.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mazda 6" Reg. No SKU5617Y Claiming Against Your Insured Reg. No. SMJ2660A			
1pc	Rear Door LH		1,312.10 X
1pc	Rear Door Sticker		38.60 X
10pcs	Rear Door Inner Trim Board Clips	5.50	55.00 X
1pc	Rear Door Weatherstrip		159.00 X
1pc	Rear Fender LH 1254.40		1,312.50 —
1pc	Rear Windscreen Moulding		105.00 —
1pc	Rear Bumper		1,265.00 —
15pcs	Rear Bumper Clips	5.50	82.50 —
1pc	Rear Bumper Corner Retainer LH		65.70 —
2pcs	Rear Bumper Tow Point Covers	(1pc) 85.10	170.20 X
1pc	Rear Bumper Reflector LH		85.10 X
1pc	Rear Wheel Bearing 302.80 20080		480.40 X
1pc	Rear Shock Absorber		354.40 X
1pc	Rear Upper Arm		248.90 X
1pc	Rear Knuckle Arm 482.30		706.90 X
1pc	Rear Trailing Arm		258.50 X
1pc	Rear Lower Arm 233.60		278.30 X
	Less 10% 20%		6,978.10
			697.81
			6,280.29
	Rear Windscreen Sealant		50.00 SN 405N
	Rear Windscreen Fastener		50.00 SN 305N
	Rear Wheel Rim LH P-?		550.00 SN
	To Dismantle / Refit Roof Lining		150.00 100d
	To Dismantle / Refit Rear Windscreen Glass		160.00 120d
	To Dismantle / Refit Rear Door Fittings / Ancillary Accessories		100.00 X
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 X
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 30d
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		180.00 160d

C/F

7,680.29

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **Allianz Global Corporate & Specialty SE, Singapore Branch**

Policy No: **Third Party**

Accident Date : 05.05.2022

Date: **20.05.2022**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mazda 6" Reg. No SKU5617Y Claiming Against Your Insured Reg. No. SMJ2660A		
		B/F	7,680.29
	To Conduct Computerize Wheel Alignment Test		80.00 <i>600</i>
	Labour Charge - Panel Beating, Repairing of Rear Fender Inner Panel, Arch Inner Panel,Cnt, Weld Rear Fender & Part Replacement		900.00 <i>700</i>
	To Respray Affected Areas		750.00 <i>600</i>
		Total :	<u>9,410.29</u>

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shiau Chan (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Wednesday, 12 April 2023 10:37 AM
To: Kenneth Kong (LKKAUTO)
Cc: Shiau Chan (LKKAUTO)
Subject: FW: SKU5617Y | Acc date: 05.05.2022
Attachments: Image_001.jpg

2nd reminder.

Dear Kenneth,

We propose count as normal and close at L/S – 4,970 and 6 days.

Attached is the quotation from supplier.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Chew Goon Motor(ad3)
Sent: Friday, 10 February 2023 2:35 PM
To: Kenneth Kong LKK Auto
Subject: FW: SKU5617Y | Acc date: 05.05.2022

Gentle reminder.

Dear Kenneth,

We propose count as normal and close at L/S – 4,970 and 6 days.

Attached is the quotation from supplier.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Chew Goon Motor(ad3)
Sent: Friday, 20 January 2023 3:51 PM
To: Kenneth Kong LKK Auto
Subject: SKU5617Y | Acc date: 05.05.2022

Dear Kenneth,

We propose count as normal and close at L/S – 4,970 and 6 days.

Attached is the quotation from supplier.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

18/05 2022 WED 17:30 FAX

001/001

趙源摩哆**Chew Goon Motor**

新加坡宏茂橋第 2A 工業區第五道大牌十號門牌十五,十六,十七(一樓)及門牌五(三樓)

Blk 10 Ang Mo Kio Industrial Park 2A, Ave 5

#01-15, 16 & 17 AMK Autopoint, Singapore 568047

Business Reg. No. : 221880/00C GST Reg. No. : MX-0486007-AO

Tel : 6484 1626 (24 Hrs) Fax : 6484 0465

E-mail : chewgoon@singnet.com.sg

◀ 修理各种汽车打吗咭喷漆等 ▶

TO : JAE DATE : 18.05.2022

ATTN : Alan TEL : 64179795

FROM : Kelly FAX : 67450616

TOTAL PAGE : 1/1 OUR REF : SKU5617Y

CHASSIS : JM6GJ1072G0211221

Engine no : PE20663981

MAKE & MODEL : Mazda 6 YEAR : 2015

PLEASE LIST PRICE : (GENUINE PARTS)

1	Rear Door LH	1312-10
2	Rear Door Sticker	14-70+23-90
3	Rear Fender LH	1312-50
4	Rear Wheel Bearing	480-40
5	Rear Shock Absorber	354-40
6	Rear Upper Arm	248-90
7	Rear Knuckle Arm	706-90
8	Rear Trailing Arm	258-50
9	Rear Lower Arm	278-30

List price. Thanks

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
11 Day &
Recovery After Paim
6 days

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: Third Party

Accident Date : 05.05.2022

Date: 20.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mazda 6" Reg. No SKU5617Y Claiming Against Your Insured Reg. No. SMJ2660A			
1pc	Rear Door LH		R 1,312.10 X
1pc	Rear Door Sticker		nn 38.60 X
10pcs	Rear Door Inner Trim Board Clips	5.50	nn 55.00 X
1pc	Rear Door Weatherstrip		nn 159.00 X
1pc	Rear Fender LH		R 1,312.50 X
1pc	Rear Windscreen Moulding		nn 105.00 X
1pc	Rear Bumper		nn 1,265.00 X
15pcs	Rear Bumper Clips	5.50	nn 82.50 X
1pc	Rear Bumper Corner Retainer LH		DIT 65.70 X
2pcs	Rear Bumper Tow Point Covers	(nr) 85.10	nn 170.20 X
1pc	Rear Bumper Reflector LH		nn 85.10 X
1pc	Rear Wheel Bearing		480.40 X
1pc	Rear Shock Absorber		354.40 X
1pc	Rear Upper Arm		248.90 X
1pc	Rear Knuckle Arm		706.90 X
1pc	Rear Trailing Arm		258.50 X
1pc	Rear Lower Arm		278.30 X
			6,978.10
	Less 10%		697.81
			6,280.29
	Rear Windscreen Sealant		nn 50.00 SN 40sn
	Rear Windscreen Fastener		nn 50.00 SN 30sn
	Rear Wheel Rim LH		nn 550.00 SN
	To Dismantle / Refit Roof Lining		150.00 10d
	To Dismantle / Refit Rear Windscreen Glass		160.00 12d
	To Dismantle / Refit Rear Door Fittings / Ancillary Accessories		nn 100.00 X
	To Dismantle / Refit Trunk Compartment Boards & Trims		nn 80.00 X
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 30d
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		180.00 76d

C/F

7,680.29

Phone Number:

Fax Number:

Customer:

Company:

License No:

Odometer:

CHEW GOON MOTOR

SKU5617Y

165534KM

Date:

25/5/2022 4:48:22 PM

VIN

Technician:

Order No.:

VEHICLE ALIGNMENT REPORT

MAZDA, 2020, MAZDA 6

Primary Angles

			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	-----	5.30°	7.30°	-----
		Right	-----	5.30°	7.30°	-----
	Camber	Left	-0.30°	-1.28°	0.72°	-0.30°
		Right	-0.52°	-1.28°	0.72°	-0.52°
	Toe	Left	-0.09°	-0.08°	0.25°	-0.09°
		Right	0.54°	-0.08°	0.25°	0.54°
		Total	0.45°	-0.16°	0.50°	0.45°
Rear	Camber	Left	-1.06°	-1.82°	0.18°	-1.06°
		Right	-0.89°	-1.82°	0.18°	-0.89°
	Toe	Left	1.26°	-0.08°	0.25°	1.26°
		Right	0.22°	-0.08°	0.25°	0.22°
		Total	1.48°	-0.16°	0.50°	1.48°
	Thrust Angle		-0.52°	-----	-----	-0.52°

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Included Angle	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Out On Turns	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Maximum Turns	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Setback	Front	-0.12"	-----	-----	-0.11"
	Rear	-0.29"	-----	-----	-0.29"
Track Width Diff.		-0.43"			-0.44"
Wheel Base Diff.		0.17"			0.18"
Front Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Rear Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Frame Angle					-----