

ASS. RE. BY:

Tough

REF:

CS6/AS2200 4909/T43.

ASSIGNMENT

Lot 2030 Dec.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: hba

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 975K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC2504E Yr Regn: 2010 / Dec.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco 1.4cc 1390Colour: blue A/C: Insured / Std / NI / NASp. Reading: 187377 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ15ZBV01533

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R19R: N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at

Success United

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 25/5/22

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : CST No. 200402570G

Allianz Insurance (S) Pte Ltd
 3 Temasek Ave #09-01 Centennial Towers
 Singapore 039190

Attention : Motor Claim Department
 Contact : 62972529

Estimate : SU220053

Date : 20/05/2022
 Vehicle Num. : SMC2504E
 Make/Model : Volkswagen Scirocco-2010
 Chassis/Eng# : WVVZZZ13ZBV015332/CAV233249
 Accident Date : 17/05/2022
 Claim No. :
 Reference :
 Policy No. : SP2000700564 (15/12/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :				
1.	1 pc	Frt Bonnet	680.00	bt ✓
2.	1 pc	Frt Bonnet Hinge LH	65.00	?
3.	1 pc	Frt Bonnet Mechanism Lock	150.00	x
4.	1 pc	Frt Fender LH	390.00	bt ✓
5.	1 pc	Frt Fender Inner Panel LH	1,200.00	Rp
6.	1 pc	Frt Fender Inner Liner LH	120.00	de ✓
7.	1 pc	Frt Bumper Assy	650.00	in ✓
8.	1 pc	Frt Bumper Side Holder LH	28.00	de ✓
9.	1 pc	Frt Bumper Bracket LH	30.00	?
10.	1 pc	Frt Bumper Inner Sponge	120.00	?
11.	1 pc	Frt Bumper Reinforcement	350.00	?
12.	1 pc	Frt Bumper Foglamp LH	150.00	?
13.	1 pc	Frt Bumper Foglamp Garnish LH	125.00	de ✓
14.	1 pc	Frt Bumper Signal Lamp LH	95.00	cut ✓
15.	1 pc	Frt Bumper Lower Centre Air Grille	170.00	cut ✓
16.	1 pc	Frt Grille Assy	200.00	cut ✓
17.	1 pc	Headlamp Assy LH	490.00	cut ✓
18.	1 pc	Headlamp Panel LH	110.00	bt ✓
19.	1 pc	Horn	70.00	x
Total Parts Purchased S\$:			5,193.00	
10.00% Of The Above Parts S\$:			519.30	
Based On Cost Plus S\$:			5,712.30	
SPECIAL NETT ITEMS :				
1.	1 set	Frt Fender Inner Liner Clips	30.00	2over ✓
2.	1 set	Frt Bumper Clips	30.00	net ✓
Special Nett Total S\$:			60.00	

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

Allianz Insurance (S) Pte Ltd
 3 Temasek Ave #09-01 Centennial Towers
 Singapore 039190

Attention : Motor Claim Department
 Contact : 62972529

Estimate : SU220053

Date : 20/05/2022
 Vehicle Num. : SMC2504E
 Make/Model : Volkswagen Scirocco-2010
 Chassis/Eng# : WVVZZZ13ZBV015332/CAV233249
 Accident Date : 17/05/2022
 Claim No. :
 Reference :
 Policy No. : SP2000700564 (15/12/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	150.00	30
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	800.00	600
		To putty and respray painting on affected area.	800.00	700
		Labour Total S\$:		1,750.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

Tanjin 97425749/62563561
 20/5/22 21045
 Ex: t69, Not Authorise
 05 days
 Lumpsum, Resurvey after repair
 tanjin@lkkauto.com

Total S\$: 7,522.30

=====


 SUCCESS UNITED PTE LTD